



BMW 3 BERLINE: [REDACTED]

Vinnumber:	WBASV31010FL09154	Versionname:	318dA (100 kW)
First Registrationdate:	18/03/2021	Fiscalpower:	
Expertise Mileage:	156629	Power Kw:	100
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3508
Fueltype:	Hybrid Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/45/18/92 H				
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/45 R 18 92 H
Tyre size FR				225/45 R 18 92 H
Tyre size RL				225/45 R 18 92 H
Tyre size RR				225/45 R 18 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	53,44
Bumper moulding F, Crack, Replace and paint	53,44



Bumper F, Scratch(es), Acceptable 0,00



Windscreen, Scratch(es), Polish 0,00



Alloy rim RL polished, Rust, Acceptable 0,00



Door RL, Scratch(es), Acceptable 0,00



Wing RL, Dent(s), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Alloy rim FR polished, Rust, Acceptable 0,00



Door RR, Dent(s) and scratch(es), Acceptable 0,00

