



VOLKSWAGEN TIGUAN: GV-980-GH

Vinnumber:	WVGZZZ5N8RW054884	Versionname:	VOLKSWAGEN TIGUAN 2.0 TDI 150 DSG7 LIFE PLUS
First Registrationdate:	22/02/2024	Fiscalpower:	VP [5P] bva 7-150CH-8cv (SUV)
Expertise Mileage:	129023	Power Kw:	110
Bodytype:	SUV	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Grey
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Grey
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Roof bar black	
Steering wheel leather		Rear view camera	
Type of climate control	Autom climate control	Seat cover lining	Lining Other

Tyres

215/65/17/99 V			
Summer tyres:	Fr.L.	Dunlop: 40%	Fr.R.
	Re.L.	Firestone: 35%	Re.R.
			Firestone: 25%
Tyre profile depth FL			5.5
Tyre profile depth FR			5.1
Tyre profile depth RL			5.8
Tyre profile depth RR			6.5
Tyre size FL			215/65 R 17 99 V
Tyre size FR			215/65 R 17 99 V
Tyre size RL			215/65 R 17 99 V
Tyre size RR			215/65 R 17 99 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			257
Tyre make FR			257
Tyre make RL			258
Tyre make RR			258

Assistance equipment

Spare wheel	Yes	Jack	Yes
Air vent L, Broken, Replace			



Interior, Stain, Cleaning



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Alloy rim RL, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Door FL, Dent(s), Repair and paint (complete)



Wing FL, Dent(s), Acceptable



Door RL, Dent(s), Acceptable



Wing RL, Dent(s), Repair and paint (complete)



Wing trim RL, Scratch(es), Replace



Roof pillar L, Dent(s), Acceptable



Bonnet, Hail damage, Repair and paint (complete)



Wing RR, Scratch(es), Paint



Door RR, Scratch(es), Paint



Bumper R, Scratch(es), Paint



Rear spoiler, Dent(s), Repair and paint (complete)



Roof, Hail damage, Repair and paint (complete)



Historique Maintenance

Immatriculation: **GV-980-GH** Date de 1ère immatriculation: **22/02/2024**

Modèle: **Volkswagen TIGUAN 2.0 TDI 150 DSG7 LIFE PLUS VP [5P] bva 7-150CH-8cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
26/05/2026	125.554	JEAN LAGARDE TRELISSAC	REVISION ET CLIM
	0		POMPE A EAU RPLT
	0		PLAQUETTES AR RPLT
	0		PLAQUETTES AV RPLT
	0		HUILE BV RPLT
	0		PILE DE CLE RPLT
	0		BALAIS ESSUIE GLACE AV
10/11/2025	92.004	JEAN LAGARDE	ADBLUE
	0		REVISION ET CLIM ET AIR ET CARBURANT
05/05/2025	60.673	JEAN LAGARDE	PLAQUETTES AR RPLT
	0		ADBLUE
	0		DISQUES PLAQUETTES AV RPLT
	0		REVISION ET CLIM
	0		BALAI ESSUIE GLACE AR
20/03/2025	56.076	PROFIL PLUS	REPARATION DE ROUE
22/10/2024	33.443	PROFIL PLUS	REMPLACEMENT PNEUS ETE
03/10/2024	30.735	JEAN LAGARDE	PLAQUETTES AV RPLT
	0		BALAIS ESSUIE GLACE AV
	0		REVISION