



2-FHA-988


2-FHA-988 · ST Line 1.0i EcoBoost 125pk M6 · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FHA-988	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF02XXERK2RA31424
Model	Puma	Cylinder Capacity	999 ^{cm3}
Model Versions	ST Line 1.0i EcoBoost 125pk M6	Transmission Type	Handmatig geschakelde transmissie
		First Admission	07-05-2024
Body Type	5 door hatchback	Odometer	73.554 ^{Km}
Color	Grey	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2024	Number Headrests	5
KW	92		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Leather steering wheel

Navigation system

Rear parking sensors

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs

Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Left	5 ^{mm}	Bridgestone	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Front Right	5 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Right	5 ^{mm}	Bridgestone	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Spare Tire Type	Compressor					


Damages



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Skirt - Right	Dislocated / Loose	Rubber	Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Small scratch(es)	Touch-up / Polish	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Right	Small dent(s)	Restyle	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Dislocated / Loose	Wielkuipbescherming	Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Skirt - Left	Dislocated / Loose	Rubber	Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Left	Small dent(s)	Restyle	No



Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Small scratch(es)	Touch-up / Polish	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Dislocated / Loose	Repair	No





Damage Part

Damage Type

Repair Type

Acceptable

Tailgate

Small dent(s)

Restyle

No



Damage Part

Damage Type

Notes

Repair
Type

Acceptable

Tailgate

Missing

Ruitenwisserkapje

Replace

No



Damage Part

Damage Type

Notes

Repair
Type

Acceptable

Roof

Missing

Antenne

Replace

No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Handgriep	Replace	No