



Expertise

Protocol number: 46661140
Order No. / Reference: 26760916
Inspection date: 22 Jul 2026

Manufacturer: Opel

Model: Corsa-e GS

VIN: VXKUHZKXZP4019244



Vehicle details

Manufacturer / Type / Model / Equipment

Opel Corsa-e GS	
Vehicle Identification number	VXKUHZKXZP4019244
Mileage (Read)	11,143 km
First registration	30 May 2023
Number of holders	1
Fuel type	Electric
Power	57 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Arktis Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Red



Vehicle details

Maintenance booklet / proof	Available / incomplete	Next maintenance in	20,800 km
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ377900
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1889 / ABX 00031		
Emission standard	2017/1151	fine dust sticker	
Permitted total weight	1,920 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/55 R16 91H	All-season tyres on Light alloy	Goodyear	6mm / 6mm
2)	195/55 R16 91H	All-season tyres on Light alloy	Goodyear	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- Storage compartments (storage compartment in the center console, front and rear - cup holder in the center console - glove compartment - storage compartment in the front doors, suitable for 1.5-liter beverage bottles - storage compartment in the rear doors, suitable for 0.5-liter beverage bottles)
- Active Pedestrian Warning System (AVAS)
- Anti-lock braking system (ABS) (with cornering brake control (CBC) and brake assist)
- Hill Start Assist
- On-board computer
- Braking system: Regenerative
- Electronic brake force distribution (EBD)
- Driver information display 7", color (fully digital)
- Electric windows front and rear (with one-touch function and anti-pinch protection)
- Pedestrian protection
- Intelligent speed control and limiter
- Transmission: Automatic electric drive with fixed gear ratio
- Back window, heater
- Rear window wiper (with intermittent function)
- Child safety lock in the rear doors, manual
- Automatic climate control (recirculation mode, manual - automatic air distribution - sun position sensor - activated carbon filter - rear footwell heating)
- Paint finish: Solid
- LED daytime running lights
- LED taillights
- Steering wheel made of vegan synthetic leather, flattened at the bottom.
- Headlight range adjustment, manual
- myOpel App, with Corsa-Electric specific functions (battery charge level indicator and range monitoring - remote control of climate control and charging settings)
- Onboard charger (vehicle-integrated charging unit, single-phase (7.4 kW))
- Parkpilot, rear parking aid (with acoustic warning signal when reversing)
- Quickheat rapid heating system
- Tire pressure warning
- Wheels: 6.5 J x 16 alloy wheels in 5-spoke design in silver/black (low rolling resistance tires, 195/55 R16)
- Keyless Start system
- Power steering (speed-dependent)
- Seat belts: Three-point seat belts in all seats (belt force limiter and belt tensioner in the front and on the outer rear seats - warning tone and light for unfastened seat belts in all seats)
- Visibility equipment (rain sensor, front - automatic dimming headlights with tunnel detection - interior rearview mirror, automatically dimming)
- Adaptive brake light
- Airbag: Front airbags, driver and front passenger (front passenger airbag can be manually deactivated)
- Airbag: Front and rear head airbags
- Airbag: Side airbag for driver and front passenger side (side airbag, front passenger, deactivatable)
- Aluminum sports pedals
- Electrically adjustable and heated exterior mirrors for driver and passenger side (manually foldable - exterior mirror housing in black)
- third brake light
- Headliner, Black
- Electronic Stability Program Plus (ESP Plus)
- Driving modes: 3 adjustable (ECO, Normal and Sport)
- Front collision warning with automatic emergency braking and pedestrian detection (Active between 5 and 85 km/h. Monitors the distance to the vehicle ahead; if the vehicle approaches a vehicle or pedestrian too quickly, the driver is alerted by a warning tone and a display in the driver information screen. In case of a collision risk, the braking system is prepared and, if necessary, emergency braking is initiated to minimize the consequences of a potential collision.)
- Headrests (5) (Height adjustable)
- Paintwork: Roof in contrasting black
- Charging cable: Mode 2 charging cable (Type 2, up to 1.8 kW - for household sockets - 6 meters length)
- LED headlights (LED daytime running lights - high beam assist - LED turn signals in exterior mirrors)
- Steering column, height and reach, adjustable
- Lithium-ion battery (50 kWh storage capacity)
- Driver fatigue detection (Based on steering behavior and driving duration, it detects signs of possible driver fatigue and issues a visual and audible warning (3-stage warning).)
- Electric parking brake
- Pollen filter
- Upholstery: Cloth
- Radio: Multimedia radio with 7" color touchscreen display (automatic music recognition (title, album, artist, cover) for audio devices with USB connection, Bluetooth audio streaming, hands-free calling via Bluetooth interface, phonebook and call list display, smartphone integration via Apple CarPlay, Android Auto, voice control (e.g., navigation (Google Maps, Apple Maps), music, phone, reading and dictating text messages), 1 USB port in the center console, steering wheel controls, dual tuner, graphic equalizer, 6 speakers)
- Seats: Comfort passenger seat (4-way manually adjustable (length and backrest angle))
- Seats: Rear seat backrest split 60:40, foldable
- Solar Protect heat-insulating glazing (in the rear, heavily tinted)
- Lane Keeping Assist (warning in case of unintentional lane departure (between 65 km/h and 180 km/h) via a warning light in the driver information display. The Lane Keeping Assist also alerts the driver by gently counter-steering, but does not continuously steer the vehicle.)



- Seats: Front sports seats (driver's seat, 6-way manually adjustable (length, height, backrest angle) - passenger seat, 4-way manually adjustable (length, backrest angle))
- 12V power outlet in the center console, front
- Traction Control (TC) Plus (traction control with engine and brake intervention)
- Ambient lighting
- Traffic sign recognition (recognition of speed limits and their cancellation, as well as display of the recognized sign in the driver information display (depending on visibility and weather conditions))
- Immobiliser
- Central locking with remote control

- Pre-installation for ISOFIX child seat mounting system (on the front passenger seat)
- Pre-wiring for child seat mounting system "ISOFIX" (rear outer)

Extra equipment

- Paint finish: Solid special color
- Onboard charger (vehicle-integrated charging unit, 3-phase (11 kW))
- Park & Go (Parkpilot, front and rear parking aid with audiovisual warning - blind spot warning - electrically folding exterior mirrors)
- Tires: All-weather tires 195/55 R16
- Heated seats, driver and passenger

- Navigation system: Multimedia navigation system with 7" touchscreen color display (Multimedia Radio Navigation: - Navigation system with integrated memory - Road map of Europe (including Russia and Turkey) - 3D map display - Dynamic route guidance via map and/or arrow display - Display of points of interest - Tour planning - GPS module)
- Wheels: All-weather tires 195/55 R16

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Trim / covers (Hutablagen Halterung) - Missing - Replace
2	Door - front right side	Door handle - outside - Scratch(es) - Smart repair
3	Wheel / tyres	Tyre - front right side - Scratch(es) - Replace
4	Door - rear right side	Door - Scratch(es) - Smart repair
5	Roof	Roof - Dent / paintcoat damage - Smart repair
6	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Replace
7	Rear bumper	Rear bumper - Scratch(es) - Paint
8	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
9	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Side panel - rear left side	Side panel - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Navigation



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.





Figure 25: Misc.



Figure 26: Misc.



Damage 1: Trim / covers: Trim / covers (Hutablagen Halterung) - Missing - Replace



Damage 1: Trim / covers: Trim / covers (Hutablagen Halterung) - Missing - Replace



Damage 2: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 2: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 3: Wheel / tyres: Tyre - front right side - Scratch(es) - Replace



Damage 3: Wheel / tyres: Tyre - front right side - Scratch(es) - Replace



Damage 3: Wheel / tyres: Tyre - front right side - Scratch(es) - Replace



Damage 4: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 4: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 5: Roof: Roof - Dent / paintcoat damage - Smart repair



Damage 5: Roof: Roof - Dent / paintcoat damage - Smart repair



Damage 5: Roof: Roof - Dent / paintcoat damage - Smart repair



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 8: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 8: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 8: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 9: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 9: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 9: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 9: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint