



Expertise

Protocol number: 46051328
Order No. / Reference: 26502834
Inspection date: 19 Jun 2026

Manufacturer: Mercedes-Benz

Model: E 300 de T 9G-TRONIC

VIN: W1K2132161A950584



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz E 300 de T 9G-TRONIC	
Vehicle Identification number	W1K2132161A950584
Mileage (Read)	131,761 km
First registration	27 Feb 2021
Number of holders	1
Power / Engine displacement	143 kw / 1,950 ccm
Fuel type / Cylinder	Hybr.D/E ext.aufl / 4
Gearbox / Number of gears	Automatic / 9
Type of drive	Rear drive
Type of vehicle	Station wagon
Colour / colour code	Polarweiß
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	166 Tag(e)
Last service on / at	11/2025 at 119,789 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA340296
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / AEN 00025		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,820 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100V	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	275/40 R18 103V	Winter tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100W	Summer tyres on Light alloy	unterschiedliche Hersteller	4mm / 4mm
2)	275/40 R18 103Y	Summer tyres on Light alloy	Continental	4mm / 4mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ADAPTIVE BRAKE with hill start assist, pre-filling and drying braking in wet conditions
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Foldable armrest for driver and front passenger
- Left and right exterior mirrors, heated and electrically adjustable, painted in body color
- Brake assist, active
- Tachometer
- DYNAMIC SELECT
- EASY-PACK tailgate
- Electronic Stability Program (ESP)
- Chassis: Air suspension on the rear axle with level control
- Vehicle Setup
- Electric window regulator with comfort operation and anti-pinch protection, 4-way
- Heated rear window with timer
- Climate: Pre-conditioning
- Communication module (LTE) for the use of Mercedes me connect services
- Charging cable for household socket, 4m, coiled, 1-phase, TYPE E/F CEE 7/7
- Steering wheel: Multifunction sports steering wheel in Nappa leather
- Mercedes-Benz emergency call system
- Package: Interior lighting package
- Upholstery: Marseille fabric, black
- Radio: Audio 20
- Trip computer and on-board computer
- Service interval indicator ASSYST
- Seats: i-Size child seat attachment
- Seats: Front seats electrically adjustable
- Cruise control
- Electronic immobilizer
- Central locking
- AdBlue container with a volume of 25 liters
- Airbag for driver and front passenger
- Airbag: Kneebag for driver
- Airbag: Windowbags left/right
- Traction control (ASR)
- ATTENTION ASSIST
- Exterior mirror housings with integrated ambient lighting
- Basic services
- Diesel particulate filter
- Third brake light
- EASY-PACK cargo cover including EASY-PACK safety net
- ECO start/stop function
- Chassis: AGILITY CONTROL chassis with selective damping system
- Vehicle key in high-gloss black with matte chrome trim.
- Transmission: 9-speed automatic, 9G-TRONIC
- LED taillights
- KEYLESS START
- THERMATIC automatic climate control
- Headrests 5-way adjustable for driver and front passenger, 4-way adjustable, and 2-way adjustable in the rear.
- LED High Performance Headlights
- Steering column mechanically adjustable in height and length
- Center console piano black finish
- Package: Standard Exterior Equipment
- PRE-SAFE system
- Tire pressure monitoring system
- Windscreen wipers with rain sensor
- Power steering
- Seats: Rear seat backrests foldable, 40/20/40 split
- Power outlet: 12V socket in the cargo area
- High-visibility vest for drivers
- Green, heat-insulating glass all around
- Decorative elements, silver effect lacquer



Extra equipment

- Adaptive Highbeam Assist
- Black fabric headliner
- Paint finish: Special solid colors
- Package: Acoustic Comfort Package
- Package: Parking package with reversing camera (The parking package with reversing camera makes it easier to find and select parking spaces, as well as to park and exit in parallel and perpendicular parking spaces or garages. The active parking assistant steers the vehicle into parking spaces, including speed control and automatic gear changes.)
- Radio accessories: Burmester surround sound system (with 13 speakers, a 9-channel DSP amplifier and a total system output of 590 W. 13 high-performance speakers and electronic and acoustic elements precisely tuned to the interior ensure first-class Burmester sound. The surround function or sound optimization for the front and rear seats makes the listening experience even more immersive.)
- Power outlets: 2 USB ports in the rear with charging function (Electrical devices such as smartphones or tablets can be connected to the vehicle and charged using the 2 USB ports in the rear. They are located in the rear part of the center console.)
- Towbar with ESP trailer stabilization (When not in use, the towbar can be electrically swivelled behind the rear bumper. To couple a car trailer or mount a bicycle carrier, it is electrically swivelled out again and automatically locked in the operating position.)
- Package: Public Charging
- Package: Sun protection package (mechanical sunshade in the rear doors - extendable, side-swiveling sun visors with make-up mirror for driver and front passenger)
- Package: Mirror package (Interior and exterior mirrors on the driver's side automatically dimming, exterior mirrors left and right electrically folding with parking position on the right, and ambient lighting in the exterior mirrors. Both exterior mirrors can be electrically folded in and out at the touch of a button to protect the mirror housing from damage, for example when parking. For improved visibility and safety, the exterior mirror on the driver's side and the interior mirror dim automatically and continuously.)
- Sunroof: Panoramic electric sunroof in glass design (with comfort and automatic rain closing, PRE-SAFE closing function, electric sunshade and anti-pinch protection)
- Telephone accessories: Multifunctional telephony (this equipment perfectly integrates the mobile phone into the vehicle - it connects the device to the external antenna and charges the mobile phone - both without cables or a cradle.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Front bumper	Front bumper - Scratched - Smart repair
2	Body	Underbody panelling - Broken / torn - Replace



Wear and tear

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear right side - Scratched - No deduction
2	Wheel / tyres	Alloy rim - front left side - Scratch(es) - No deduction
3	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
4	Bonnet	Bonnet - Stone chips - No deduction
5	Vehicle glazing	Windscreen - Stone chips - No deduction
6	Door - rear left side	Door - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 12 Apr 2026	1.015,54 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Comments

Wartungshistorie gemäß Auftraggeber Informationen.

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Damage 1: Front bumper: Front bumper - Scratched - Smart repair




Damage 1: Front bumper: Front bumper - Scratched - Smart repair



Damage 2: Body: Underbody panelling - Broken / torn - Replace




Damage 2: Body: Underbody panelling - Broken / torn - Replace




Wear and tear 4: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 4: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 5: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 5: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 6: Door - rear left side: Door - Scratch(es) - No deduction



Wear and tear 6: Door - rear left side: Door - Scratch(es) - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1K2132161A950584

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ E 300 de T 9G-TRONIC

Datum	KM-Stand	Beschreibung
26.11.2025	119.789	Regelwartungsdienst
22.11.2024	95.327	Regelwartungsdienst
11.04.2024	85.166	HU + AU
13.11.2023	78.201	Regelwartungsdienst
05.01.2023	52.728	Bremsflüssigkeit ern; Motoröl b. Wartung; Regelwartungsdienst
08.02.2022	25.455	Regelwartungsdienst