


**Vehicle details**

VIN	WVGZZZE2Z MP011128	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate		Model	ID.4 77kWh 1ST Auto	Maintenance mileage	-
Registration date	11/05/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	129 167 km	Engine size	-	interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

**Inspection Details**



**Generic equipment**

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓






**Removable element**

Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

**Technical Document**

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

## Tyres

Continental 235/50/20 Summer 5.0 mm			Continental 235/50/20 Summer 5.5 mm	
Continental 235/50/20 Summer 4.0 mm			Continental 235/50/20 Summer 4.0 mm	

## Exterior

<p><b>1</b></p>  <p>● ●</p> <table border="0"> <tr><td>Part</td><td>Step plate</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Step plate	Position	Back left	Damages	Scratched	Severity	-	Repair mode	For info	<p><b>2</b></p>  <p>● ●</p> <table border="0"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) &gt; 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Back left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Step plate																				
Position	Back left																				
Damages	Scratched																				
Severity	-																				
Repair mode	For info																				
Part	Door																				
Position	Back left																				
Damages	Dented																				
Severity	Diameter (mm) > 20																				
Repair mode	Smart Repair																				
<p><b>3</b></p>  <p>● ●</p> <table border="0"> <tr><td>Part</td><td>Roof wind deflector</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Roof wind deflector	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	<p><b>4</b></p>  <p>● ●</p> <table border="0"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Roof	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair
Part	Roof wind deflector																				
Position	-																				
Damages	Chemical deposit																				
Severity	-																				
Repair mode	Lumpsum repair																				
Part	Roof																				
Position	-																				
Damages	Chemical deposit																				
Severity	-																				
Repair mode	Lumpsum repair																				
<p><b>5</b></p>  <p>● ●</p> <table border="0"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Back right	Damages	Scratched	Severity	-	Repair mode	Repair	<p><b>6</b></p>  <p>● ●</p> <table border="0"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Front right	Damages	Scratched	Severity	-	Repair mode	Repair
Part	Door																				
Position	Back right																				
Damages	Scratched																				
Severity	-																				
Repair mode	Repair																				
Part	Bumper																				
Position	Front right																				
Damages	Scratched																				
Severity	-																				
Repair mode	Repair																				