

» Overview

Order number: 1002350026
Order completed: 09.03.2026 14:05
Report number: 10186962
VIN: WVGZZZ5N7PW040679



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	SUV
Make:	Volkswagen
Model:	Tiguan
Manufacturers and type code:	0603 / BZG
Date of first registration:	09.01.2023
Mileage:	147,651 km
Proof of mileage:	ReadOff
Exterior colour:	Deep Black Perleffekt
Roof colour:	Deep Black Perleffekt
Propulsion:	Front
Fuel:	Diesel
Engine size (cc):	2,000 ccm
Performance:	110 kW (150 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	4
Euronorm:	Euro 6
Number of doors:	4
Number of seats:	5
Gearbox:	Automatic 7-speed
Upholstery type:	Lining Alcantara
Interior colour:	Storm Grey-Titanschwarz/Titanschwarz/ Schwarz/Storm Grey
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	01.2026
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	None
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	
Remainder until next maintenance:	0 KM

12 V outlet in center console in rear and in luggage compartment	Digital radio reception DAB+
2 LED reading lights in front and 2 in rear	Disc brakes in front
2 USB-C ports in the front, charging capacity up to 45 W	Disc brakes in rear
3 head restraints in rear	Diversity antenna for FM reception
30-color ambient lighting	Door and side trim panel
3-point seat belt for center rear seat	Drawers under front seats
3-point seat belts in front with height adjustment and seat belt pretensioners	Driver alert system
3-point seat belts with seat belt pretensioners for the outer rear seats	Driver and front passenger airbag with front passenger airbag deactivation, including knee airbag on driver side
4 alloy wheels "Frankfurt" 7J x 18	Driving on the right
4-cylinder diesel engine 2.0 l	Dual-clutch transmission DSG DQ381
4-cylinder diesel engine 2.0 l TDI, 110 kW	Dynamic headlight range control with dynamic cornering light
7-speed automatic transmission or dual-clutch transmission DSG, note: PR family EDF	Dynamic Road Sign Display
8 speakers	Electric auxiliary air heater
Adaptive Cruise Control ACC stop & go incl. speed limiter	Electric luggage compartment opening and closing, adjustable opening angle
Air Care Climatronic 3 zone automatic climate control w/ allergen filter, enhanced air filter a. controls in rear	Electromechanical parking brake with Auto Hold function
AirStop® tires 235/55 R18, rolling resistance class A	Electromechanical speed-sensitive power steering
Alternator 140 A	Electronic engine sound
App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto	Electronic immobilizer
Aspherical exterior mirror on driver side	Electronic Stability Control w/ driver steering recommendation, ABS, ASR, EDL, EDTC and trailer stabilization
Auto-dimming interior rearview mirror	Elimination of nameplate for engine designation on luggage compartment lid
Automatic headlight control with LED separate daytime running light and exit and entry lighting	Elimination of Tire Mobility Set
Automatically-heated washer nozzles in front	Emergency call service; no registration required, service is activated upon delivery
Autonomous Emergency Braking Front Assist (for Adaptive Cruise Control ACC up to 210 km/h)	Emission standard EU6 AP
Basic equipment variant	Equipment options subset for Germany
Battery 420 A (70 Ah)	Exterior mirrors power-adjustable and heated
Body-colored bumpers, black lower parts, Silver Gray center part in front, chrome elements in rear	First aid kit, warning triangle and safety vest
Body-colored exterior mirror housings and door handles	Front center armrest height- and longitudinally adjustable, with storage compartment and vents in rear
Business Premium package incl. navigation system	Front seats with height adjustment
Carpet mats in front and rear	Front stabilizer bar
Carrier frequency 433.92 MHz-434.42 Mhz	Front-wheel drive
Central locking system without SAFELOCK, with radio remote control and 2 remote control folding keys	Fuel system for diesel engine
Chrome elements on the mirror switch and power window switches, door pulls; interior door handle in matte chrome	Gearshift knob in leather
Chrome trims on the side windows	Hatchback
Completely folding front passenger seat backrest	Headliner
Cornering light and poor weather light	Heated front seats
Curtain airbag system for front and rear passengers incl. side airbags in front	High-beam control Light Assist
Decorative inserts "Cross" for dashboard and front door trim panels	Illuminated front scuff plates, in aluminum
	Illuminated vanity mirrors in sun visors
	Initial standard fuel filling

Inserts of front seats and outer rear seats in ArtVelours microfleece	Rear fog lamp
Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer	Rear shock absorption, basic version 1
ISOFIX anchorage points for mounting of 2 child seats on rear bench seat, also for i-Size child seats	Rear stabilizer bar
Laminated safety glass windshield, heat- and sound-insulating	Refrigerant R1234yf
Lane keeping system Lane Assist	Regional code " ECE " for radio
Leather multi-function steering wheel, heated, with shift paddles	Remote unlocking for rear seat backrest
LED license plate lighting	Right exterior mirror, convex
LED matrix headlamps with LED separate daytime running light and dynamic cornering light	Safety-optimized front head restraints, longitudinally and height adjustable
Left-hand drive	Service indicator 30 000 km or 2 years (variable)
Light unit in front footwell	Shock absorption in front
LongLife Service Regime	Silver-anodized roof rails
Luggage compartment floor	Small navigation system M&I (Media & Internet package)
Luggage compartment lamp	Special identification label for EC for M1 passenger vehicles
Lumbar supports in front	Sports equipment
Manual in German (Germany)	Standard battery/alternator capacity
Mobile phone interface "Comfort" with inductive charging feature	Standard climatic zones
Multi-color Digital Cockpit Pro, selection of different info profiles possible	Standard manufacturing sequence
Multifunction camera	Standard paint coating
Navigation system "Discover Media" incl. Streaming & Internet	Standard pedal cluster
No special edition	Standard wheel bolts
No special purpose vehicle, standard equipment	Start-stop system with regenerative braking
Non-smoker's package: Storage compartment and 12 V outlet in front	Suspension range 12 installation control only, no requirement forecast
Not hot country	Tire Pressure Monitoring System
Online service, with OCU, with head unit coding, without engine immobilizer interconnection	Tires without specification of tire brand
Operating permit, alteration	Tool kit
Operating voltage 12 V	Transport protection film (minimum protection) with additional transport protection measures
Overhead storage compartment	Trims for alloy wheels
Park Distance Control - warning signals for obstacles in the front and rear	Two-tone horn
Part set without country-specific prescriptive standard	Type approval country Germany
Pedestrian Monitoring	Vehicle class differentiation -550-
Premium comfort seats in front	Vehicles with special upgrade measures
Preparation for We Connect and We Connect Plus	Voice control
Privacy glass for rear side windows and rear window	Warning lamp for washer fluid level
Proactive passenger protection system in combination with Front Assist	Warning signal and warning lamp for front and rear seat belts not fastened
Radio	Weight range 6 installation control only, no requirement forecast
Rain sensor	Wheelbase
Rear bench seat asymm. split folding, longitudinally movable and folding with load-through hatch and center armrest	Without activated carbon canister with SCR
Rear combination lamps	Without Adaptive Chassis Control
Rear exhaust tailpipe (standard)	Without additional front underbody guard
	Without additional tires
	Without alternative drive system

Without auxiliary heater/parking heater
Without camera systems/accident sensors
Without charging cable
Without decals and emblems
Without delivery equipment
Without ECO function
Without electric motor (hybrid)
Without electronic steering column lock
Without fire extinguisher
Without folding table on front seat backrest
Without headlamp washer system
Without head-up display
Without hill start assist/hill descent control/comfort driving assist
Without lane change assist
Without license plate carrier
Without mode 3 charging cable
Without partition
Without rear spoiler
Without roof insert (standard roof)
Without seat ventilation/massage seat
Without second battery
Without special body measures
Without tie down straps/net/pocket
Without trailer hitch

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Continental	Front	Left	Summer	Aluminium	235/55 R 18 100 V	5.0 mm
Continental	Front	Right	Summer	Aluminium	235/55 R 18 100 V	5.0 mm
Continental	Rear	Left	Summer	Aluminium	235/55 R 18 100 V	5.0 mm
Continental	Rear	Right	Summer	Aluminium	235/55 R 18 100 V	5.0 mm

Permitted: Yes

Roadworthy: Yes

» Devaluation Factors

Nr	Location	Damage type	Repair type
1	Bumper F	Deformed / Strained	Replace and paint
2	Alloy rim RL	Deformed / Strained	Replace Safety relevant damage
3	Door FL	Dent(s)	Repair and paint (complete)
4	Door FR	Dent(s) and scratch(es)	Repair and paint (complete)
5	Service	Maintenance	Execute
6	Bumper R	Dent(s) and scratch(es)	Repair and paint (complete)
7	Wing FL	Dent(s)	Repair and paint (complete)
8	Side window RR	Scratch(es)	Replace
9	Preparationtime bodywork	Paint preparation	Execute
10	Door RL	Misalignment	Dismount/Mount
11	Wing trim FL	Deformed / Strained	Replace Safety relevant damage
12	Door trim FL	Broken	Replace Safety relevant damage
13	MOT certificate	Expired	Renew
14	Boot lid covering R	Scratch(es)	Replace
15	Door RL	Scratch(es)	Smart repair
16	Wheel arch cover FL	Deformed / Strained	Replace
17	Boot lid covering R	Scratch(es)	Replace
18	Rubber seal for boot lid	Tearred	Replace
19	Boot carpet	Dirty	Chemical cleaning
20	Tailgate / Boot	Dent(s)	Paintless dent repair
21	Wing trim RL	Misalignment	Dismount/Mount
22	Engine protection plate	Residue	Cleaning
23	Door RR	Scratch(es)	Polish

» Usage Damages

Nr	Location	Damage type	Repair type
1	Door seal FL	Damaged	Acceptable
2	Bonnet	Stone chip(s)	Acceptable
3	Door panel FL	Scratch(es)	Acceptable

» Commercial devaluation

Accidental vehicle:	Yes
Known previous damages:	Yes
Previous damages detectable:	No
Repainting present:	Yes
Repainting professionally executed:	Yes
Paint thickness measurement performed:	Yes - with abnormalities/deviations

Nr	Location	Damage	Repair type	Repair cost
1	Other	Fully comprehensive harm		€ 8,721.58
Total without VAT:				€ 8,721.58

PAINTHICKNESS MEASUREMENT RESULTS

Part	Paint (µm)
Paint thickness Door FL (µm)	250.0
Paint thickness Wing RL (µm)	1,030.0

At least 3 measurements were carried out per component.

» Notes On The Assessment

Details of the assignment and the scope of the assessment:

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WVGZZZ5N7PW040679

VIN checked and matches documentation

Vehicle condition:

Poor general condition

Inspection condition:

Sufficient

Lifting platform/lifting equipment used:

Yes

Testdrive carried out:

No

Engine test carried out:

Yes

» Remarks

This copy was generated electronically. It is valid without an original signature.

Additional notes on the condition report:

(09.03.2026 14:05) Fahrzeughistorie konnte nicht geprüft werden.

» Commercial Pictures



Front Left 3/4



Front Right 3/4




Rear Left 3/4




Rear Right 3/4




Mileage



Sill outer L



Sill outer R




Chassis nr



Wheel FL



Wheel FR




Wheel RL




Wheel RR



Central console




Engine compartment



Documents



Interior arrangement




Registration Certificate




Paint thickness Door FL




Paint thickness Wing RL




History Maintenance




Interior - front



Interior - rear



Underbody scan




GPS/Radio

» Devaluation Damages

DEVALUATION FACTORS

1 - Bumper F - Deformed / Strained - Replace and paint

Comment	Kostenerweiterung möglich
---------	---------------------------



2 - Alloy rim RL - Deformed / Strained - Replace
Safety relevant damage



3 - Door FL - Dent(s) - Repair and paint (complete)




4 - Door FR - Dent(s) and scratch(es) - Repair and paint (complete)




5 - Service - Maintenance - Execute

Comment	seit 15000Km fällig
---------	---------------------


6 - Bumper R - Dent(s) and scratch(es) - Repair and paint (complete)



7 - Wing FL - Dent(s) - Repair and paint (complete)



8 - Side window RR - Scratch(es) - Replace



9 - Preparationtime bodywork - Paint preparation - Execute

10 - Door RL - Misalignment - Dismount/Mount

Comment



Einstellen, Prüfen, Kostenerweiterung möglich




11 - Wing trim FL - Deformed / Strained - Replace
Safety relevant damage




12 - Door trim FL - Broken - Replace
Safety relevant damage



13 - MOT certificate - Expired - Renew




14 - Boot lid covering R - Scratch(es) - Replace



15 - Door RL - Scratch(es) - Smart repair




16 - Wheel arch cover FL - Deformed / Strained - Replace




17 - Boot lid covering R - Scratch(es) - Replace

Comment

Verkleidung Schloßträger




18 - Rubber seal for boot lid - Teared - Replace





19 - Boot carpet - Dirty - Chemical cleaning



20 - Tailgate / Boot - Dent(s) - Paintless dent repair





21 - Wing trim RL - Misalignment - Dismount/Mount




22 - Engine protection plate - Residue - Cleaning

Comment

Kostenerweiterung möglich




23 - Door RR - Scratch(es) - Polish





USAGE DAMAGES

1 - Door seal FL - Damaged - Acceptable



2 - Bonnet - Stone chip(s) - Acceptable



3 - Door panel FL - Scratch(es) - Acceptable

