MACADAM








Peugeot 2008 (UKL): 2BGJ439

Vinnumber:	**VR3UDYHZSMJ876130**	Versionname:	**2008 Allure Pack 1.5 BlueHDi S&S 130pk/cv 5p EAT8**
First Registrationdate:	**16/11/2021**	Fiscalpower:	
Expertise Mileage:	**167727**	Power Kw:	**96**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
Type of Maintenance book	**Digital maintenance**	Type of Tow bar	**Tow bar removable**
Type of GPS storage	**N.A.**		

Tyres

Summer tyres:	**215/70/17/96 H**			
	Fr.L.	**Continental: 4 mm**	Fr.R.	**Goodride: 4 mm**
	Re.L.	**Continental: 5 mm**	Re.R.	**Continental: 5 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**215/70 R 17 96 H**
Tyre size FR	**215/70 R 17 96 H**
Tyre size RL	**215/70 R 17 96 H**
Tyre size RR	**215/70 R 17 96 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**3590204**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Seat cover FL, Deformed / Strained, Acceptable







Engine insulation, Tear, Replace



Boot lid covering R, Scratch(es), Smart repair







Internal boot lining R, Scratch(es), Acceptable




Internal boot lining L, Scratch(es), Smart repair




Bumper moulding R, Scratch(es), Acceptable





Door trim RR, Scratch(es), Replace




Onderhoudshistorie van: VR3UDYHZSMJ876130

ALPHABET

Kenteken	2BGJ439
Merk Model	Peugeot 2008 Allure Pack 1.5 BlueHDi S&S 130pk/cv 5p EAT8
Brandstofsoort	Diesel
Datum deel1	11/16/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/14/26	152,782	diagnose	Uitvoeren
4/14/26	152,782	nokkenas	Repareren
3/5/26	150,142	luchtfilter interieur	Vervangen
3/5/26	150,142	oliezeef	Vervangen
3/24/25	120,142	120000 km	Uitvoeren
3/24/25	120,142	luchtfilter interieur	Vervangen
3/24/25	120,142	oliezeef	Vervangen
3/24/25	120,142	remvloeistof	Vervangen
3/24/25	120,142	riem of multiriem	Vervangen
3/24/25	120,142	ruitenwisserrubber vooraan	Vervangen
6/14/24	91,431	90000 km	Uitvoeren
6/14/24	91,431	luchtfilter interieur	Vervangen
6/14/24	91,431	oliezeef	Vervangen
6/14/24	91,431	ruitenwisserrubber achter	Vervangen
6/14/24	91,431	ruitenwisserrubber vooraan	Vervangen
8/10/23	60,189	60000 km	Uitvoeren
8/10/23	60,189	brandstof hoofdfilter	Vervangen
8/10/23	60,189	luchtfilter	Vervangen
8/10/23	60,189	luchtfilter interieur	Vervangen
8/10/23	60,189	oliezeef	Vervangen
8/10/23	60,189	ruitenwisserrubber vooraan	Vervangen
10/14/22	29,089	30000 km	Uitvoeren
10/14/22	29,089	luchtfilter interieur	Vervangen
10/14/22	29,089	oliezeef	Vervangen