



Peugeot 308 (UKL): 2CFG222

Vinnumber:	VR3FRHNSTNY572092	Versionname:	308 SW GT 1.2 PureTech S&S 130pk/cv 5p EAT8
First Registrationdate:	1/07/2022	Fiscalpower:	
Expertise Mileage:	59879	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/40/18/92 Y			
Summer tyres:	Fr.L.	Firestone: 7 mm	Fr.R.	Firestone: 7 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL	7.0			
Tyre profile depth FR	7.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	5.0			
Tyre size FL	225/40 R 18 92 Y			
Tyre size FR	225/40 R 18 92 Y			
Tyre size RL	225/40 R 18 92 Y			
Tyre size RR	225/40 R 18 92 Y			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	258			
Tyre make FR	258			
Tyre make RL	261			
Tyre make RR	261			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover FL, Worn, Acceptable





Engine insulation, Damaged, Replace



Bumper F, Scratch(es), Spot repair



Bonnet, Dent(s), Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Alloy rim RL polished, Chemical polution, Acceptable



Charging cable (fast), Missing, Check



Charging cable (normal), Missing, Check



Bumper R, Scratch(es), Acceptable



Bumper moulding R, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Kenteken	2CFG222
Merk Model	Peugeot 308 SW GT 1.2 PureTech S&S 130pk/cv 5p EAT8
Brandstofsoort	Benzine
Datum deel1	7/1/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
10/7/25	46,682	40000 km	Uitvoeren
10/7/25	46,682	batterij	Vervangen
10/7/25	46,682	bougie	Vervangen
10/7/25	46,682	luchtfilter	Vervangen
10/7/25	46,682	luchtfilter interieur	Vervangen
10/7/25	46,682	oliezeef	Vervangen
10/7/25	46,682	remblokken vooraan	Vervangen
10/7/25	46,682	universele lampen	Vervangen
9/19/24	30,771	30000 km	Uitvoeren
9/19/24	30,771	luchtfilter interieur	Vervangen
9/19/24	30,771	oliezeef	Vervangen
9/19/24	30,771	remvloeistof	Vervangen
7/27/23	14,712	luchtfilter interieur	Vervangen
7/27/23	14,712	oliezeef	Vervangen
7/27/23	14,712	onderhoud 1e jaar	Uitvoeren
7/27/23	14,712	ruitenswisserrubber vooraan	Vervangen
7/27/23	14,712	universele lampen	Vervangen