DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	VR3USHNSX RJ756428	Registration date	16/07/2024	Exterior Color	Unknown
Brand	PEUGEOT	Licence Plate	FRI-MJ 195	Odometer	33 590 km
Model	2008 PureTech 130 EAT8 Allure				

Inspection Details

Arrival Date	12/08/2026	Inspection ID	7115778	Inspection date	17/08/2026
Assign Date	12/08/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys AKB Lüdersfeld



Generic equipment

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓
Radio user manual	✓

Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Service	✓


Tyres

Goodyear 215/60/17 H All seasons 7.0 mm

Goodyear 215/60/17 H All seasons 7.0 mm

Goodyear 215/60/17 H All seasons 7.0 mm

Goodyear 215/60/17 H All seasons 7.0 mm





Exception / Damage

1



Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	-

DEKRA

DEKRA Automotive Solutions

Appraisal Report

2		Part	Bonnet	Repair Time	-	Part Cost	-
		Position	Front	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	15.00%
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	**Net Cost**	**-**
3		Part	Windscreen	Repair Time	-	Part Cost	-
		Position	Front	Repair Cost	-	Gross Cost	-
		Damages	Stone impact	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	**Net Cost**	**-**
4		Part	Engine soundproofing	Repair Time	0.10	Part Cost	74.53€
		Position	Front	Repair Cost	14.00€	Gross Cost	88.53€
		Damages	Cut	Paint Time	-	Depreciation %	15.00%
		Severity	-	Paint cost	-	Depreciation	- 13.28
		Repair mode	Replace	Flat Rate	-	**Net Cost**	**75.25€**
5		Part	Engine soundproofing	Repair Time	0.10	Part Cost	87.53€
		Position	Front	Repair Cost	14.00€	Gross Cost	101.53€
		Damages	Cut	Paint Time	-	Depreciation %	15.00%
		Severity	-	Paint cost	-	Depreciation	- 15.23
		Repair mode	Replace	Flat Rate	-	**Net Cost**	**86.30€**

Summary Inspection

Gross Price	190.06€	Depreciation	-28.51€	Net Price	161.55€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	0.20	28.00€	15.00 %	-4.20€	23.80€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	162.06€	15.00 %	-24.31€	137.75€
Flat Rate	0.00€	-	-	0.00€