MACADAM








BMW 330e Touring: 2ATN127

Vinnumber:	**WBA6N31060FK57668**	Versionname:	
First Registrationdate:	**9/07/2021**	Fiscalpower:	
Expertise Mileage:	**153179**	Power Kw:	
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Hybrid Petrol**		
Maintenance	**OK**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of headlighting	**Headlighting LED**		
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/50/17/98 Y**			
	Fr.L.	**Continental: 6 mm**	Fr.R.	**Continental: 6 mm**
	Re.L.	**Continental: 7 mm**	Re.R.	**Continental: 7 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**7.0**
Tyre profile depth RR	**7.0**
Tyre size FL	**225/50 R 17 98 Y**
Tyre size FR	**225/50 R 17 98 Y**
Tyre size RL	**225/50 R 17 98 Y**
Tyre size RR	**225/50 R 17 98 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**1**		
Number of charging cables (rapid charge)	**1**		

Bumper F, Scratch(es), Repair and paint (complete)









Alloy rim RL, Scratch(es), Acceptable





Wing RL, Dent(s), Acceptable





Door RL, Dent(s), Acceptable


Bumper R, Scratch(es), Acceptable




Alloy rim RR, Scratch(es), Acceptable




Door FR, Dent(s) and scratch(es), Repair and paint (complete)




Wing FR, Scratch(es), Repair and paint (complete)




Bodywork, Paint measurement, Acceptable



Roof, Dent(s), Acceptable



MACADAM

MACADAM
