

# Mercedes-Benz \* Citan '12

## Vehicle information

Make:	<b>Mercedes-Benz</b>	License:	
Gearbox:	<b>MAN 6 VIT</b>	Body color:	
Model:	<b>* Citan '12</b>	VIN:	<b>W1V4156051U294660</b>
Fuel type:	<b>Diesel</b>	Power:	<b>70 kW</b>
Version:	<b>Citan 109CDI L3H1 H GB</b>	First registration	<b>31/05/2021</b>
Mileage:	<b>210057 km</b>	N° of doors:	

## Damage summary

<b>Front</b>	3
<b>Interior</b>	2
<b>Left</b>	2
<b>Rear</b>	5
<b>Right</b>	2
<b>Roof &amp; others</b>	1

## Commercial pictures





### Options according to the inspector

Central consol F

Yes Hook

Yes Radio multimedia

Yes

### Damages

#### Bonnet

Dent(s)

Repair and paint (complete)

Front



**Boot door panel RL**  
Dent(s) and scratch(es)  
Repair and paint (complete)  
Rear



**Boot door panel RR**  
Dent(s) and scratch(es)  
Repair and paint (complete)  
Rear



**Bumper corner RL**  
Scratch(es)  
Repair and paint (complete)  
Rear



**Bumper F**  
Scratch(es)  
Repair and paint (complete)  
Front



**Door FL**  
Dent(s) and scratch(es)  
Repair and paint (complete)  
Left



**Door FR**

Dent(s) and scratch(es)  
Repair and paint (complete)  
Right



**Ignition key**

Missing  
Replace  
Interior

**Roof**

Dent(s)  
Repair and paint (complete)  
Roof & others



**Sliding door R**

Dent(s) and scratch(es)  
Repair and paint (complete)  
Right



**User's manual**

Missing  
Replace  
Interior

**Wheel aperture RL**

Dent(s) and scratch(es)  
Repair and paint (complete)  
Rear



**Wheel aperture RR**

Deformed / Strained  
Repair and paint (complete)  
Rear



**Windscreen**

Stone chip(s)  
 Replace  
 Front

**Wing RL**

Dent(s) and scratch(es)  
 Repair and paint (complete)  
 Left

**Tyres****Front Left**

Summer  
 195/65/15/91/H  
 Michelin  
 3.5 mm

**Front Right**

Summer  
 195/65/15/91/H  
 Michelin  
 3.9 mm

**Rear Left**

Summer  
 195/65/15/91/H  
 Michelin  
 6.1 mm

**Rear Right**

Summer  
 195/65/15/91/H  
 Michelin  
 5.9 mm

**Checks**

Certificate of Conformity	<b>No</b> CO2 Emission	<b>155</b>
Digital maintenance	<b>Yes</b> GPS storage	<b>N/A</b>
Luggage cover	<b>N/A</b> Number head rests	<b>2</b>
Number of charging cables (rapid charge)	<b>0</b> Number of keys total	<b>1</b>
Service book	<b>N/A</b> User's manual	<b>No</b>

#### Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.