

INSPECTION REPORT




End of contract

GENERAL INFO

File	316947
License plate	1YVK524
Vehicle identification number	WAUZZZF20MN047366
Dossier	2020 210 063
Make	Audi A6 35 TDI Bus.Ed.Str.Spor
Mileage	83904
First registration	04/01/2021
client availability date	03/07/2026
inspectionDate	13/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
35	Front Bonnet // Polish	Y
40	Windshield // Repair	Y
81	Door Front Left // Smart Repair Medium	Y
133	Bumper Rear // Painting	Y
202	Rocker Panel Right // Painting	Y
222	Side View Mirror Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
336	Tyre Rear Right // Replace	N
340	Wheel Two Tone Front Right // Repair	N


Damage Pictures



Bumper Rear // Painting-scratch



Door Front Left // Smart Repair Medium-scratch




Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Painting-scratch



Rocker Panel Right // Painting-scratch



Side View Mirror Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch




Wheel Two Tone Rear Right // Repair-scratch



Tyre Rear Right // Replace-cracked



Windshield // Repair-cracked



Front Bonnet // Polish-Chemical reaction