



Expertise

Protocol number: 46557915  
Order No. / Reference: 26575023  
Inspection date: 16 Jul 2026

|                        |                                                                    |
|------------------------|--------------------------------------------------------------------|
| Manufacturer: Ford     | Model: Focus Turnier 1.0 EcoBoost Start-Stopp-System Aut. ACTIVE X |
| VIN: WF0PXXGCHPMG59517 |                                                                    |



| Vehicle details                                                  |                           |
|------------------------------------------------------------------|---------------------------|
| Manufacturer / Type / Model / Equipment                          |                           |
| Ford Focus Turnier 1.0 EcoBoost Start-Stopp-System Aut. ACTIVE X |                           |
| Vehicle Identification number                                    | WF0PXXGCHPMG59517         |
| Mileage (Read)                                                   | 149,090 km                |
| First registration                                               | 24 Sept 2021              |
| Number of holders                                                | 1                         |
| Power / Engine displacement                                      | 92 kw / 999 ccm           |
| Fuel type / Cylinder                                             | Petrol / 3                |
| Gearbox / Number of gears                                        | Automatic / 8             |
| Type of drive                                                    | Front drive               |
| Type of vehicle                                                  | Station wagon             |
| Colour / colour code                                             | Obsidian-Schwarz Metallic |
| Doors / Seats                                                    | 5 / 5                     |
| Upholstery type                                                  | Cloth                     |
| Colour of upholstery                                             | Anthracite-Black          |



| Vehicle details                              |                              |                         |                                                            |
|----------------------------------------------|------------------------------|-------------------------|------------------------------------------------------------|
| Maintenance booklet / proof                  | digital proof / complete     | Next maintenance in     | 85 %                                                       |
| Last service on / at                         | 03/2026 at 146,690 km        |                         |                                                            |
| Key is / should be                           | 2 / 2                        | FZG documents           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                              |                              | Letter No.              | GD573232                                                   |
| Previous damage / Accident                   | Detectable                   | Repainting              | Detectable                                                 |
| Inspection conditions                        | sufficient                   | Lifting equipment / pit | yes                                                        |
| Test drive                                   | Not performed                | Engine function test    | Performed                                                  |
| Manufacturer key number/<br>type code number | 8566 / BPP 00562             |                         |                                                            |
| Emission standard                            | EURO6;WLTP;AP;PI/CI; M, N1 I | fine dust sticker       |                                                            |
| Permitted total weight                       | 1,970 kg                     | Empty weight            |                                                            |

| Tyres            |                |                             |              |             |
|------------------|----------------|-----------------------------|--------------|-------------|
| Mounted tyres    |                |                             |              |             |
| #                | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
| 1)               | 215/55 R17 98V | Winter tyres on Light alloy | Continental  | 6mm / 6mm   |
| 2)               | 215/55 R17 98V | Winter tyres on Light alloy | Continental  | 6mm / 6mm   |
| Additional tyres |                |                             |              |             |
| #                | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
| 1)               | 215/55 R17 94V | Summer tyres on Light alloy | Continental  | 4mm / 4mm   |
| 2)               | 215/55 R17 94V | Summer tyres on Light alloy | Continental  | 4mm / 4mm   |
| Replacement      |                |                             |              |             |
| Typ              | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|                  | Tirefit        | Expiration date 05/2025     |              |             |

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

## Equipment

### Standard equipment

- Airbag: Passenger airbag deactivation
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Tires: 7 J x 17 alloy wheels (4) with 215/55 R 17 tires
- Black woven fabric headliner
- Roof spoiler painted in car color
- Tachometer
- Electronic Safety and Stability Program (ESP)
- Driving mode switch, selective
- Chassis: Chassis with 30 mm increased ground clearance
- Ford Easy Fuel
- Ford Power Start function
- Luggage compartment lighting
- Luggage compartment floor, adjustable in two ways
- Cruise control
- Illuminated glove compartment
- Back window, heater
- Interior lighting with LED technology
- Intelligent security system
- Headrests: 2 front and 3 rear, height adjustable
- LED fog lights
- Steering wheel: 3-spoke design
- Make-up mirrors in driver and passenger sun visors
- MyKey key system (individually programmable second key)
- Emergency brake light
- Otto particulate filter
- Package: Comfort
- Front and rear parking pilot system
- Upholstery: Cloth
- Pre-Collision Assist
- Tire Pressure Monitoring System (TPMS)
- Headlight assistant with day/night sensor
- Electromechanical power steering
- Seats: Passenger seat height-adjustable, manually
- Seats: Map grid on the driver's and front passenger's seat backrests
- Start-stop system
- Carpet floor mats front and rear, velour
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Heat-insulating glazing, tinted
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Mounting points behind the second row of seats
- Crossover body kit
- Roof rails, black
- Digital instrument panel 12.3" (31.2 cm screen diagonal)
- Electronic Shifter
- Driver information system
- Lane keeping assist including lane keeping assist
- Electric windows front and rear
- Electric parking brake with auto-hold function
- Ford ECO-Coach
- FordPass Connect including eCall, live traffic information (only with navigation) and Wi-Fi hotspot
- Speed limiter
- Transmission: 8-speed automatic transmission
- Tailgate, electric and sensor-controlled
- rear window wiper
- Instrument lighting, adjustable
- Isofix bracket
- Radiator grille with honeycomb design
- LED daytime running lights
- Adjustable steering column
- Center console "Premium" front
- Navigation: Ford Navigation, Ford SYNC 3 with AppLink, 8" touchscreen (20.3 cm) with DAB/DAB+
- Package: Family
- Package: View
- Pollen filter and dust filter
- Post-Collision Assist
- Tire repair kit
- Rear view camera
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Seats: Driver's seat height adjustable
- Seats: Rear seat backrest
- Seats: Front sports seats with enhanced lateral support
- 12-volt power outlet in the luggage compartment
- Black trim around the side windows
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats
- Central/Double Locking

### Extra equipment

- Swiveling towbar (incl. ESP trailer stabilization)
- Charging station for mobile devices (inductive)
- Safety partition net for luggage compartment
- Paint finish: Metallic
- Package: Winter (heated windscreen - heated steering wheel - individually and variably heated front seats)



## Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |

## Value reducing factors

| No. | Component group        | Description                                                |
|-----|------------------------|------------------------------------------------------------|
| 1   | Equipment              | Tirefit filler - Expired - Replace                         |
| 2   | Sill - left side       | Sill - Scratch(es) - Smart repair                          |
| 3   | Mudguard - left side   | Mudguard - left side - Scratch(es) - Smart repair          |
| 4   | Door - rear left side  | Door - Scratch(es) - Smart repair                          |
| 5   | Front bumper           | Spoiler - Deformed - Replace                               |
| 6   | Fog lamp               | Fog lamp - front right side (Rahmen) - Scratched - Replace |
| 7   | Door - front left side | Door - Scratch(es) - Paint                                 |

## Wear and tear

| No. | Component group | Description                                  |
|-----|-----------------|----------------------------------------------|
| 1   | Misc.           | Main inspection - No evidence - No deduction |
| 2   | Rear bumper     | Rear bumper - Scratch(es) - No deduction     |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Previous damages

| No. | Previous damage                                                 | Extent of damage (Net) |
|-----|-----------------------------------------------------------------|------------------------|
| 1   | Rear, Side - left, Provided by user / customer, from 2 Mar 2022 | 3.971,35 €             |

## Repainting

| No. | Repainting                                                                               |
|-----|------------------------------------------------------------------------------------------|
| 1   | Door - rear left side, Professionally carried out, Invoice of repair done Non-existent   |
| 2   | Door - front left side, Professionally carried out, Invoice of repair done Non-existent  |
| 3   | Door - front right side, Professionally carried out, Invoice of repair done Non-existent |

## Paint coat thickness measurement

|                         |        |                        |        |
|-------------------------|--------|------------------------|--------|
| Door - rear left side   | 154 µm | Door - front left side | 148 µm |
| Door - front right side | 186 µm |                        |        |



## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
*(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
*(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



**Figure 1:** Diagonal front (left)



**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace




**Damage 2:** Sill - left side: Sill - Scratch(es) - Smart repair




**Damage 2:** Sill - left side: Sill - Scratch(es) - Smart repair



**Damage 3:** Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



**Damage 3:** Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



**Damage 3:** Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



**Damage 4:** Door - rear left side: Door - Scratch(es) - Smart repair




**Damage 4:** Door - rear left side: Door - Scratch(es) - Smart repair




**Damage 5:** Front bumper: Spoiler - Deformed - Replace




**Damage 5:** Front bumper: Spoiler - Deformed - Replace




**Damage 5:** Front bumper: Spoiler - Deformed - Replace



**Damage 5:** Front bumper: Spoiler - Deformed - Replace



**Damage 5:** Front bumper: Spoiler - Deformed - Replace



**Damage 6:** Fog lamp: Fog lamp - front right side (Rahmen) - Scratched - Replace



**Damage 6:** Fog lamp: Fog lamp - front right side (Rahmen) - Scratched - Replace



**Damage 6:** Fog lamp: Fog lamp - front right side (Rahmen) - Scratched - Replace



**Damage 7:** Door - front left side: Door - Scratch(es) - Paint



**Damage 7:** Door - front left side: Door - Scratch(es) - Paint




**Damage 7:** Door - front left side: Door - Scratch(es) - Paint



**Damage 7:** Door - front left side: Door - Scratch(es) - Paint



**Damage 7:** Door - front left side: Door - Scratch(es) - Paint



**Damage 7:** Door - front left side: Door - Scratch(es) - Paint



**Repainting 1:** Door - rear left side



**Repainting 2:** Door - front left side



**Repainting 3:** Door - front right side



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0PXXGCHPMG59517

Hersteller / Modell: FORD FORD Focus Turnier 1.0 EcoBoost Start-Stopp-System Aut. ACTIVE X

| Datum      | KM-Stand | Beschreibung                                                                                                                                                                                                                             |
|------------|----------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 30.03.2026 | 146.690  | Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges                                                                                                                                                                           |
| 03.07.2025 | 222.849  | Reparatur Sonstiges; Systemtest/Eigendiagnose; Turbolader ern                                                                                                                                                                            |
| 04.06.2025 | 123.139  | Bremse Sonstiges; Systemtest/Eigendiagnose                                                                                                                                                                                               |
| 02.05.2025 | 119.640  | Batterie ern; Systemtest/Eigendiagnose                                                                                                                                                                                                   |
| 03.04.2025 | 117.271  | Getriebeöl ern/prüfen; Motoröl b. Wartung                                                                                                                                                                                                |
| 26.03.2025 | 117.271  | AU; Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v;<br>Bremsscheiben vorne; Luftfiltereinsatz ern; Motor ern; Regelwartungsdienst;<br>Reparatur Sonstiges; Systemtest/Eigendiagnose; Wartung Sonstiges;<br>Zündkerzen ern |
| 27.06.2024 | 111.177  | Keilrippenriemen; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Reparatur<br>Sonstiges; Reparatur Sonstiges; Reparatur Sonstiges; Systemtest/<br>Eigendiagnose; Wartung Sonstiges; Zahnriemen/Steuerkett ern                              |
| 04.04.2024 | 106.654  | Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben + Klötze h;<br>Bremsscheiben hinten                                                                                                                                                  |
| 13.11.2023 | 89.662   | Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern;<br>Regelwartungsdienst; Reparatur Sonstiges; Systemtest/Eigendiagnose;<br>Wartung Sonstiges                                                                    |
| 17.03.2023 | 58.949   | Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v;<br>Bremsscheiben vorne; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern;<br>Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern                                |
| 22.08.2022 | 29.866   | Motoröl b. Wartung; Regelwartungsdienst; Systemtest/Eigendiagnose                                                                                                                                                                        |