MACADAM







Seat Arona (UKL): 2EGE401

Vinnumber:	**VSSZZZKJ4PR133078**	Versionname:	**Arona Move 1.0TSi 95pk/cv 5p**
First Registrationdate:	**2/10/2023**	Fiscalpower:	
Expertise Mileage:	**56999**	Power Kw:	**70**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 5 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**plus 2900 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/60/16/96 H**			
	Fr.L.	**Vredestein: 4 mm**	Fr.R.	**Vredestein: 3 mm**
	Re.L.	**Vredestein: 5 mm**	Re.R.	**Vredestein: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**205/60 R 16 96 H**
Tyre size FR	**205/60 R 16 96 H**
Tyre size RL	**205/60 R 16 96 H**
Tyre size RR	**205/60 R 16 96 H**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**2480**
Tyre make FR	**2480**
Tyre make RL	**2480**
Tyre make RR	**2480**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Instrument panel, complete, Not functioning (well), Check




Seat cover FL, Stain, Cleaning




Bumper F, Scratch(es), Acceptable






Door FL, Dent(s), Acceptable




Roof pillar L, Dent(s), Paintless dent repair




Shutter / cover R, Missing, Repair/replace (lump sum)







Bumper moulding R, Scratch(es), Smart repair




Bumper R, Scratch(es), Repair and paint (complete)








Door RR, Scratch(es), Acceptable




Outside rear-view mirror housing R, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Acceptable




Onderhoudshistorie van: VSSZZZKJ4PR133078

ALPHABET

Kenteken	2EGE401
Merk Model	Seat Arona Move 1.0TSi 95pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	10/2/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
8/28/25	30,170	luchtfilter interieur	Vervangen
8/28/25	30,170	oliezeef	Vervangen
8/28/25	30,170	onderhoud 12 maand	Uitvoeren
8/28/25	30,170	ruitenwisserrubber vooraan	Vervangen