


MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number			Code / Agency				Date accident 04/06/2026								
				Expert code		Adjuster code			Policy number				Injured person can recover the VAT								
Date assignment 04/06/2026		Date first survey 09/06/2026		Place MILANO		C/O VAR		Repairs TO START		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) AUDI Q5 SPORTBACK 50 TFSI e Busin. Advan								Plate GP857MJ		Vin Chassis WAUZZZFY6P2095707				First Registration 15/06/2023							
Usage status NON CONOSCIUTO		Km 69699		Tyres % 70		Color GRIGIO		Type of enamel METALLIZED/DOUBLE				Consistency of damage YES		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts * (VAT excluded)			
								Dif		Time		Dif		Time		Dif		Time		Time	
1		80A807680AFCOX		Front bumper side grille				R		S		S		S							
1		80A807062FGRU		Front bumper side spoiler				R		S		S		S							
1		80A853818AGRU		Rear wheel arch trim				R		S		S		S							
1		80A809838ASTL		Complete rear mudguard				R		G		G		G							
1		80A821105ASTL		Front mudguard				L		M		M		M							
1		80A807065BGRU		Front bumper						M		M		M							
1		80A807067HGRU		Rear bumper upper part						M		M		G							
1		80A833052CSTL		Rear door				R		M		M		M							
1		80A831052PSTL		Front door				R		L		L		L							
1		80A807679AFBMT		Front bumper side grille				L		L		L		L							
1		80A853717JGRU		Front wheel arch trim				L		L		L		L							
1		Codice Ricambio		2 Retrov est dx/sx - PRM																	
1		Codice Ricambio		Mod. porta post. - PRM				R													
1		Codice Ricambio		Mod. porta ant. - PRM				R													

New for old value (N)	Remarks Pneum. INV. Pirelli 235/60 R18. Presente cavo di ricarica; verificare dot. di serie
-----------------------	---

ALPHABET

Telaio WAUZZZFY6P2095707

GP857MJ

AUDI Q5 SPORTBACK 50 TFSI e Busin. Advan. quattro S tronic sports utility vehicle 299CV 5P automatico

Current Odo (Time of Ma	Maintenance Request	Service Type Descriptio	Maintenance Job Description
27.000	03/10/24	Tagliando a 30 000 km	Tagliando a 30 000 km
38.000	27/02/25	Maintenance	Generico
53.334	30/10/25	Tagliando a 50 000 km	***Service at 50 000 km