


Vehicle details

VIN	LRW3E7FS2 PC759769	Brand	TESLA	Maintenance date	-
Licence Plate		Model	Model 3 RWD 4d	Maintenance mileage	-
Registration date	17/04/2023	Year	2023	Exterior Color	Black Solid
Odometer	230 837 km	Engine size	-	Interior Color	Black
Fuel	Electric	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	20/07/2026	Inspection loc.	
-----------------	------------	-----------------	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Central locking	✓
Electric windows	✓
Audio System	✓
Led lighting	✓

Removable element


Vehicle charger	✓
Wireless charger	✓

Technical Document

Spare key	✓
Card Key	✓
Sat Nav CD ROM Software	✓

Tyres

Hankook 235/40/19 Summer 5.0 mm



Hankook 235/40/19 Summer 5.0 mm



Hankook 235/40/19 Summer 5.5 mm

Hankook 235/40/19 Summer 5.5 mm


Exterior

2



Part Alloy wheel 19"
Position Front left
Damages Scratched
Severity -
Repair mode Lumpsum repair

3



Part Wing
Position Front left
Damages Stone impact
Severity -
Repair mode For info

4



Part Door
Position Front left
Damages Dent & Chips
Severity -
Repair mode Repair

5



Part Alloy wheel 19"
Position Back left
Damages Scratched
Severity -
Repair mode Lumpsum repair

6



Part Door
Position Back left
Damages Scratched
Severity -
Repair mode Repair

7



Part Wing
Position Back left
Damages Dent & Chips
Severity -
Repair mode Repair

8



Part Step plate
Position Front left
Damages Dented
Severity -
Repair mode For info

9



Part Tailgate / Boot door
Position -
Damages Scratched
Severity -
Repair mode Repair

10



Part Bumper
Position Back
Damages Scratched
Severity -
Repair mode Repair

11



Part Wing
Position Back right
Damages Dent & Chips
Severity -
Repair mode Repair

12



Part Alloy wheel 19"
Position Back right
Damages Scratched
Severity -
Repair mode Lumpsum repair

13



Part Door
Position Back right
Damages Dent & Chips
Severity -
Repair mode Repair

14



Part

Door

Position

Front right

Damages

Dent & Chips

Severity

-

Repair mode

Repair

●

●

●

15



Part

Alloy wheel 19"

Position

Front right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

●

●

16



Part

Step plate

Position

Back right

Damages

Scratched

Severity

-

Repair mode

For info

●

●

17



Part

Roof post A/B/C

Position

Right

Damages

Scratched

Severity

-

Repair mode

Repair

●

●

19



Part

Wing

Position

Front right

Damages

Stone impact

Severity

-

Repair mode


For info

●

●

Interior damage

1



Part	Other interior
Position	-
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

gerookt in voertuig

Others

18



Part	Damage appraisal
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info