



Volkswagen T-Cross (UKL): 2ESA958

Vinnnumber:	WVGZZZC12PY190140	Versionname:	T-Cross Life Business 1.0TSi 110pk/cv 5p DSG7
First Registrationdate:	10/01/2024	Fiscalpower:	
Expertise Mileage:	19778	Power Kw:	81
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	plus 13100 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/60/16/96 H			
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Vredestein: 3 mm	Re.R.	Vredestein: 3 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				256
Tyre make FR				256
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Ignition key, Missing, Replace			



Backrest cover FL, Tear, Replace



Seat cover FR, Stain, Acceptable



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Chemical polution, Acceptable



Headlight R, Scratch(es), Replace



Alloy rim FL, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable



Step L, Scratch(es), Repair and paint (complete)



Door seal FL, Broken, Replace



Central pillar L, Dent(s) and scratch(es), Acceptable



Door RL, Chemical polution, Polish



Bumper R, Scratch(es), Acceptable



Roof pillar R, Scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Acceptable



Roof, Chemical polution, Polish



Bodywork, Chemical polution, Acceptable



Kenteken	2ESA958
Merk Model	Volkswagen T-Cross Life Business 1.0TSi 110pk/cv 5p DSG7
Brandstofsoort	Benzine
Datum deel1	1/10/24

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/5/26	19,724	diagnose	Uitvoeren
6/5/26	19,724	klein materiaal	
2/12/26	17,151	batterij	Vervangen
2/12/26	17,151	Inspectie met olie vervanging (vast in	Uitvoeren
2/12/26	17,151	klein materiaal	
2/12/26	17,151	luchtfILTER interieur	Vervangen
2/12/26	17,151	remvloeistof	Vervangen
2/12/26	17,151	ruitenswisserrubber achter	Vervangen
2/12/26	17,151	ruitenswisserrubber vooraan	Vervangen
2/12/26	17,151	ruitenswisservloeistof	Bijvullen/-laden