



VOLKSWAGEN T-CROSS: GY-587-BJ

Vinnumber:	WVGZZZC18RY045476	Versionname:	VOLKSWAGEN T-CROSS 1.0 TSI 115ch DSG7 VW Edition VP [5P] bva 7-116CH-6cv (SUV)
First Registrationdate:	3/07/2024	Fiscalpower:	
Expertise Mileage:	8729	Power Kw:	85
Bodytype:	SUV	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Roof bar black	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Type of climate control	Autom climate control		

Tyres

	205/55/17/91 V			
Summer tyres:	Fr.L.	Continental: 45%	Fr.R.	Continental: 45%
	Re.L.	Continental: 40%	Re.R.	Continental: 45%
Tyre profile depth FL	5.3			
Tyre profile depth FR	5.2			
Tyre profile depth RL	5.7			
Tyre profile depth RR	5.3			
Tyre size FL	205/55 R 17 91 V			
Tyre size FR	205/55 R 17 91 V			
Tyre size RL	205/55 R 17 91 V			
Tyre size RR	205/55 R 17 91 V			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	256			
Tyre make FR	256			
Tyre make RL	256			
Tyre make RR	256			

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	-----	------	-----

Inner door sill FL, Dent(s) and scratch(es), Repair and paint (complete)



Seat cover RL, Stain, Cleaning



Seat cover R, Stain, Cleaning



Remote ignition key, Missing, Repair/replace (lump sum)



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Door RL, Dent(s), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Polish



Bumper F, Scratch(es), Paint



Bumper moulding FR, Scratch(es), Polish



Bumper moulding F, Scratch(es), Paint



Bumper spoiler F, Scratch(es), Polish



Outside rear-view mirror housing R, Scratch(es), Paint



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Paint



Historique Maintenance

Immatriculation: GY-587-BJ Date de 1ère immatriculation: 03/07/2024

Modèle: Volkswagen T-CROSS 1.0 TSI 115ch DSG7 VW Edition VP [5P] bva 7-116CH-6cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
11/06/2026	8.315	ADVANCE RUEIL MALMAISON	REVISION
			LIQUIDE DE FREIN
			FILTRE CLIM RPLT