



RENAULT EXPRESS: 9729-MCF

Vinnumber:	VF1RJK00070098942	Versionname:	Confort 1.5 Blue dCi 70 kW (95 cv) furgón derivado de turismo 70kW 4P manual
First Registrationdate:	14/11/2022	Fiscalpower:	
Expertise Mileage:	55097	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Certificate of Conformity:	No		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	No		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Roof rack:	
Windows electric F:			
Cruise Control:			
Steering wheel multifunctional:			
Type of climate control:	Manual climate control		

Tyres

185/65/15/92 T				
Summer tyres:	Fr.L.	Other: 5 mm	Fr.R.	Other: 5 mm
	Re.L.	Kumho: 5 mm	Re.R.	Kumho: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				185/65 R 15 92 T
Tyre size FR				185/65 R 15 92 T
Tyre size RL				185/65 R 15 92 T
Tyre size RR				185/65 R 15 92 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				263
Tyre make FR				263
Tyre make RL				2482
Tyre make RR				2482

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Seat cover FR, Worn, Replace



Interior, Dirty, Cleaning



Steering wheel, Worn, Replace



Wing FL, Dent(s), Acceptable



Door FL, Dent(s), Acceptable



Side wall RL, Scratch(es), Acceptable



Rear light L, Broken, Replace



Bumper F, Scratch(es), Paint



Side wall RR, Dent(s), Repair and paint (complete)



Wing FR, Dent(s), Acceptable



Internal boot lining R, Scratch(es), Replace



Rear panel, Scratch(es), Repair and paint (complete)



Boot door panel RL, Scratch(es), Polish



Boot door panel RR, Dent(s), Repair and paint (complete)



Boot moulding, Missing, Replace



Bumper R, Scratch(es), Paint



Tyres, No damage, Check

