



VOLVO XC40			
Vinnumber:	YV1XZEFVKN2756008	Versionname:	VOLVO XC40 Recharge Pro 231PK 5d/p AUT (536EFRB0K119)
First Registrationdate:	4/03/2022	Fiscalpower:	
Expertise Mileage:	176491	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2611
Fueltype:	Electric		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options			
Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Sun Roof electric	
Seats F heated		Panoramic roof	
Radio multimedia		Luggage cover	
Type of headlighting	Headlighting LED	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining artificial leather and alcantara	Type of Tow bar	No Tow bar
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

235/50/19/103 V				
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				235/50 R 19 103 V
Tyre size FR				235/50 R 19 103 V
Tyre size RL				255/45 R 19 104 V
Tyre size RR				255/45 R 19 104 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Total cost ex VAT	408,42
Shutter / cover F, Scratch(es), Acceptable	0,00



Bonnet, Stone chip(s), Acceptable

0,00



Bumper spoiler F, Scratch(es), Acceptable

0,00



Step L, Dent(s), Acceptable

0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

204,21



Wing trim FL, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Wing RR, Dent(s), Acceptable

0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

204,21



Wing FR, Scratch(es), Acceptable

0,00



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------



ptable	0,00
--------	------

