

### Vehicle details

VIN	VF3VFAHKK LZ032209	Brand	PEUGEOT	Maintenance date	-
Licence Plate		Model	EXPERT Premium Long 2.0 BlueHDi 120 4d	Maintenance mileage	-
Registration date	01/04/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	121 483 km	Engine size	1997	interior Color	Grey
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	4	Gears	6		




### Inspection Details

Inspection date	21/05/2026	Inspection loc.	
-----------------	------------	-----------------	--










Generic equipment	Removable element	Technical Document
Manual air-conditioning ✓	Spare wheel (wheel & tyre) ✓	User manual ✓
Cruise control ✓		Warranty booklet ✓
GPS system ✓		Spare key ✓
Tow ✓		Remote key ✓
Metallic paint ✓		Sat Nav CD ROM Software ✓
Central locking ✓		
Electric windows ✓		
Park Distance Control ✓		
Audio System ✓		

### Tyres

Michelin 215/65/16 All seasons 6.0 mm		Michelin 215/65/16 All seasons 6.5 mm	
Vredestein 215/65/16 All seasons 9.5 mm		Vredestein 215/65/16 All seasons 9.5 mm	

Exterior

<p>1</p>  <p>● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Other bodywork</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> <tr><td colspan="2">Buitenzijde voertuig</td></tr> </table>	Part	Other bodywork	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	For info	Buitenzijde voertuig		<p>2</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Roof	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair
Part	Other bodywork																								
Position	-																								
Damages	Chemical deposit																								
Severity	-																								
Repair mode	For info																								
Buitenzijde voertuig																									
Part	Roof																								
Position	-																								
Damages	Chemical deposit																								
Severity	-																								
Repair mode	Lumpsum repair																								
<p>3</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) &gt; 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Front left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	<p>4</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Back left	Damages	Scratched	Severity	-	Repair mode	Repair		
Part	Door																								
Position	Front left																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								
Part	Door																								
Position	Back left																								
Damages	Scratched																								
Severity	-																								
Repair mode	Repair																								
<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Tailgate / Boot door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Tailgate / Boot door	Position	Back right	Damages	Scratched	Severity	-	Repair mode	Repair	<p>6</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair		
Part	Tailgate / Boot door																								
Position	Back right																								
Damages	Scratched																								
Severity	-																								
Repair mode	Repair																								
Part	Bonnet																								
Position	-																								
Damages	Chemical deposit																								
Severity	-																								
Repair mode	Lumpsum repair																								
<p>7</p>  <p>● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Windscreen</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stone impact</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Windscreen	Position	-	Damages	Stone impact	Severity	-	Repair mode	For info														
Part	Windscreen																								
Position	-																								
Damages	Stone impact																								
Severity	-																								
Repair mode	For info																								