



MERCEDES

Vinnumber:	W1K2470861J242286	Versionname:	B 250 e
First Registrationdate:	14/12/2020	Fiscalpower:	
Expertise Mileage:	131914	Power Kw:	118
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2231
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	Tow bar collapsible
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining semi-artificial leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

205/55/17/85 W				
Summer tyres:	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 17 85 W
Tyre size FR				205/55 R 17 85 W
Tyre size RL				205/55 R 17 85 W
Tyre size RR				205/55 R 17 85 W
Tyre type FL				All seasons
Tyre type FR				Summer
Tyre type RL				All seasons
Tyre type RR				Summer
Tyre make FL				2477
Tyre make FR				2477
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	1		

Total cost ex VAT:	204,21
Interior, Damaged, Acceptable:	0,00



Step L, Scratch(es), Acceptable 0,00



Roof pillar L, Dent(s), Acceptable 0,00



Tailgate / Boot, Scratch(es), Acceptable 0,00



Tailgate / Boot, Scratch(es), Acceptable 0,00




Rear window, Scratch(es), Replace 0,00



Alloy rim RR polished, Scratch(es), Acceptable 0,00



Door RR, Dent(s) and scratch(es), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

204,21



Step R, Scratch(es), Acceptable

0,00



Door FR, Scratch(es), Acceptable

0,00

