



Volkswagen Polo (UKL): 2CCG500

Vinnumber:	VVWZZZAWZNU027751	Versionname:	Polo R-Line 1.0TSi 95pk/cv 5p
First Registrationdate:	1/06/2022	Fiscalpower:	
Expertise Mileage:	31053	Power Kw:	70
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 5 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	215/45/17/91 W			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/45 R 17 91 W
Tyre size FR				215/45 R 17 91 W
Tyre size RL				215/45 R 17 91 W
Tyre size RR				215/45 R 17 91 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
GPS, Scratch(es), Repair/replace (lump sum)			



Seat cover FR, Stain, Cleaning



Floor covering FL, Hole, Replace



Interior, Not original part, Repair/replace (lump sum)




Service, Maintenance, Check



Bumper F, Scratch(es), Repair and paint (complete)




Bumper moulding F, Scratch(es), Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Replace



Tyre RL, Tear, Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Acceptable




Boot cover, Broken, Replace



Bumper R, Scratch(es), Repair and paint (complete)



Reflector, Broken, Replace



Alloy rim RR polished, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Kenteken	2CCG500
Merk Model	Volkswagen Polo R-Line 1.0TSi 95pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	6/1/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
11/14/25	27,254	diagnose	Uitvoeren
11/14/25	27,254	Inspectie met olie vervanging (vast in	Uitvoeren
11/14/25	27,254	klein materiaal	
11/14/25	27,254	luchtfilter interieur	Vervangen
11/14/25	27,254	remvloeistof	Vervangen