



Expertise

Protocol number: 46616642
Order No. / Reference: 26703191
Inspection date: 21 Jul 2026

Manufacturer: Ford

Model: Mustang Mach-E AWD

VIN: WF0TK3SU1NMA09444



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Mustang Mach-E AWD	
Vehicle Identification number	WF0TK3SU1NMA09444
Mileage (Read)	56,276 km
First registration	18 May 2022
Number of holders	1
Fuel type	Electric
Power	124 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	All-wheel drive
Type of vehicle	Saloon car
Colour / colour code	Absolute Black
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black
Vehicle with smoke odor	no



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	
Last service on / at	05/2024 at 28,884 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GK811603
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BVF 00008		
Emission standard	2017/1151	fine dust sticker	
Permitted total weight	2,640 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R19 103V	Summer tyres on Light alloy	Continental	7mm / 7mm
2)	225/55 R19 103V	Summer tyres on Light alloy	Continental	7mm / 7mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/60 R18 104H	Winter tyres on Light alloy	Pirelli	7mm / 7mm
2)	225/60 R18 104H	Winter tyres on Light alloy	Pirelli	7mm / 7mm

Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- All-wheel drive
- Towbar preparation kit (ESP trailer stabilization function)
- Dashboard with carbon-look inserts
- Electrically adjustable and heated exterior mirrors
- Tires: 7 J x 19 light alloy wheels (4) in 5-spoke Y-design (with tires 225/55 R 19)
- Brake calipers, painted red
- Theft alarm system
- Electronic Stability Program (ESP)
- Lane Assist
- Electric front and rear windows with all-around closing function
- Ford EcoCoach (shows the efficiency of current driving behavior)
- Heated windshield
- Flexible luggage compartment cover and luggage compartment lighting
- Transmission: 1-speed direct drive (Electronic Shifter (rotary switch for automatic transmission))
- Interior mirror, automatically dimming
- Intelligent Protection System (IPS)
- Map reading light at the rear
- Map pocket on the driver's and passenger's seat backrest
- Rear headrests (3) height adjustable
- Coating: Mica
- LED headlights in projection lens design (automatically height-adjustable, with integrated daytime running lights)
- Illuminated makeup mirrors in the driver's and passenger's sun visors
- Rear center armrest with two cup holders
- MyKey key system
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Pollen and dust filter
- Post-Collision Assist
- Pre-Collision Assist and Evasive Steering Assist
- Wheel arch trim in glossy black
- Reversing camera with reversing parking assistant
- Windscreen wipers with rain sensor
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Seats: Driver and passenger seats, 8-way electrically adjustable
- Seats: Comfort seats, front
- Power outlet: 12-volt connection in the luggage compartment
- Carpet floor mats front and rear, velour
- Immobiliser
- Ambient lighting, multicolor LEDs
- Anti-lock braking system (ABS)
- Electrically folding exterior mirrors
- Exterior mirrors in contrasting black color
- Tires: Tire repair kit
- third brake light
- Black woven fabric headliner
- Door sill trims with metal application
- Driver information system with digital instrument panel, 10.2" screen diagonal (25.9 cm) (with range and speed display)
- High Beam Assist, Glare-Free
- Ford KeyFree system
- FordPass Connect including eCall, live traffic information and Wi-Fi hotspot (real-time traffic information - Wi-Fi hotspot - eCall emergency call system: in the event of an accident, an emergency call is triggered and important data is transmitted)
- Rear spoiler
- Intelligent speed limiter with speed limit display
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Air conditioning with automatic temperature control
- Front headrests (2)
- Charging cable (for household sockets and public charging stations)
- Steering wheel: Multifunction leather steering wheel, heated
- Media console with two USB ports
- Mustang LED taillights
- Fatigue warning
- Front and rear parking pilot system
- Pedal assembly with aluminum pads
- Upholstery: Premium Sensico upholstery in leather/suede look in anthracite with red decorative stitching (with seat center panels in suede look)
- Tire Pressure Monitoring System (TPMS)
- Reversing camera cleaning system
- Headlights: Projection lenses (LED) Headlights with daytime running lights
- Servotronic
- Seat: Rear seat backrests, foldable, 60:40 split
- Seats: Front seats, individually and variably heated
- Traffic jam assist with Stop&Go function
- Power outlet: 12-volt connection at the front
- Telephone: Inductive charging station for mobile devices
- Electric door child safety lock
- Central locking system with overall locking function



Extra equipment

- Package: Technology Package 2 (AWD) (B&O Sound System - 560 Watt Premium Sound System with 10 speakers, including subwoofer
- Electric tailgate, sensor-controlled - Intelligent cruise control, adaptive - Active Park Assist with parallel and perpendicular parking function and semi-automated driving - Traffic sign recognition system
- 360-degree camera)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Wheel arch - Scratch(es) - Smart repair
2	Body	C-pillar - right side - dent(s) - Smart repair
3	Front bumper	Spoiler (Luftabweiser) - Deformed - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Front bumper	Bumper with Parktronic - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Damage 1: Side panel - rear left side: Wheel arch - Scratch(es) - Smart repair



Damage 1: Side panel - rear left side: Wheel arch - Scratch(es) - Smart repair



Damage 2: Body: C-pillar - right side - dent(s) - Smart repair



Damage 2: Body: C-pillar - right side - dent(s) - Smart repair




Damage 3: Front bumper: Spoiler (Luftabweiser) - Deformed - Replace



Damage 3: Front bumper: Spoiler (Luftabweiser) - Deformed - Replace



Damage 3: Front bumper: Spoiler (Luftabweiser) - Deformed - Replace



Damage 3: Front bumper: Spoiler (Luftabweiser) - Deformed - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0TK3SU1NMA09444
Hersteller / Modell: FORD FORD Mustang Mach-E AWD

Datum	KM-Stand	Beschreibung
18.05.2024	28.884	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst; Systemtest/ Eigendiagnose