



BMW 3 Reeks (KKL): 2BXY921

Vinnumber:	WBA5V31010FM86786	Versionname:	318d (G20) 2.0d 136pk/cv 4p
First Registrationdate:	5/05/2022	Fiscalpower:	
Expertise Mileage:	62845	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Maintenance	sinds 05/2026		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options


Number of keys total	2	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/60/16/96 W				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm
Tyre profile depth FL	5.0			
Tyre profile depth FR	5.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	5.0			
Tyre size FL	205/60 R 16 96 W			
Tyre size FR	205/60 R 16 96 W			
Tyre size RL	205/60 R 16 96 W			
Tyre size RR	205/60 R 16 96 W			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	255			
Tyre make FR	255			
Tyre make RL	255			
Tyre make RR	255			

Assistance equipment

Instrument panel, complete, Not functioning (well), Check



Service, Maintenance, Check



Bumper F, Scratch(es), Spot repair



Bonnet, Dent(s), Paintless dent repair



Door FL, Scratch(es), Acceptable



Door RL, Dent(s), Paintless dent repair



Bumper R, Dent(s), Repair and paint (complete)



Door RR, Dent(s), Acceptable



Bodywork, Paint measurement, Acceptable



Kenteken	2BXY921
Merk Model	BMW 318d (G20) 2.0d 136pk/cv 4p
Brandstofsoort	Diesel
Datum deel1	5/5/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/13/25	49,271	BMW/MINI service standaard omvang	Uitvoeren
5/13/25	49,271	BMW/MINI service voertuig-check	Uitvoeren
5/13/25	49,271	klein materiaal	
5/13/25	49,271	remvloeistof	Vervangen
5/13/25	49,271	ruitenwisserrubber vooraan	Vervangen
5/13/25	49,271	ruitenwisservloeistof	Bijvullen/-laden
5/13/25	49,271	service luchtfilter	Uitvoeren
5/13/25	49,271	service microfilter	Uitvoeren
5/13/25	49,271	service motorolie	Uitvoeren
11/3/23	25,838	BMW/MINI service standaard omvang	Uitvoeren
11/3/23	25,838	BMW/MINI voertuigcontrole	Uitvoeren
11/3/23	25,838	controle niveaus	Uitvoeren
11/3/23	25,838	klein materiaal	
11/3/23	25,838	ruitenwisserrubber vooraan	Vervangen
11/3/23	25,838	service microfilter	Uitvoeren
11/3/23	25,838	service motorolie	Uitvoeren