DEKRA Automotive Solutions


Appraisal Report

Vehicle details

VIN	JMZKBAC30 0A362724	Mileage	78 373 km	Engine (Fuel) Type	Hybrid petrol
Licence Plate	2FUZ970	Registration date	02/09/2024	Engine size	1490
Brand	MAZDA	Fuel level	-	Transmission	Automatic
Model	2-Hybrid-Berlina-KBAC3-2021	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Gris		

Inspection Details

Inspection date	04/11/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique



Other technical information


Refill emergency kit	✓	Service manual holder	✓
Rear parcel shelf	✓	User manual	✓
Emergency compressor kit	✗	Adapter USB	✓

Options / Equipment

Tyres

195/55/16 V Summer 5.0 mm

195/55/16 V Summer 5.0 mm



195/55/16 V Summer 5.0 mm

195/55/16 V Summer 5.0 mm




Damages

1



Part	Emergency compressor kit
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

2



Part	Warranty booklet
Position	-
Damages	Not conform
Severity	-
Repair mode	For info

3



Part	Rear parcel shelf retaining strap
Position	Back left
Damages	Missing
Severity	-
Repair mode	Replace

4



Part	Rear parcel shelf retaining strap
Position	Back right
Damages	Missing
Severity	-
Repair mode	Replace

DEKRA

DEKRA Automotive Solutions

Appraisal Report

5



Part	Bonnet
Position	-
Damages	Dented
Severity	-
Repair mode	Repair

6



Part	Bumper
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Polishing

7



Part	Door
Position	Front left
Damages	Dented
Severity	-
Repair mode	For info

8



Part	Door
Position	Back right
Damages	Dented
Severity	-
Repair mode	Repair

9



Part	Wing
Position	Front right
Damages	Dented
Severity	-
Repair mode	Repair