



Expertise

Protocol number: 46408420
Order No. / Reference: 26416747
Inspection date: 8 Jul 2026

Manufacturer: Volkswagen

Model: Golf 2.0 TDI SCR Life

VIN: WVVZZZCDZMW089493



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Golf 2.0 TDI SCR Life	
Vehicle Identification number	WVVZZZCDZMW089493
Mileage (Read)	123,676 km
First registration	24 Mar 2021
Number of holders	1
Next periodical technical inspection	05/2026
(Report on hand)	
Power / Engine displacement	85 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Uranograu
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	27,300 km
Last service on / at	10/2025 at 120,945 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA728290
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / CNY 00274		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,880 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Bridgestone	7mm / 7mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Hankook	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres on Light alloy	Hankook	6mm / 6mm
2)	205/55 R16 91V	Summer tyres on Light alloy	Hankook	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2024		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Turning brake function and evasive steering support
- Airbag: Head airbag system for front and rear passengers including front side airbags
- Electrically adjustable exterior mirrors with memory function
- third brake light
- Headliner in Storm Grey
- Diesel particulate filter and SCR catalyst
- Dual-tone signal horn
- Electric auxiliary air heater
- Electronic parking brake including auto-hold function
- Automatic headlight control, with LED daytime running lights
- Windscreen made of laminated safety glass, heat and sound insulating
- Transmission: 6-speed manual transmission
- Rear window wiper with intermittent function
- ISOFIX mounting points
- rear headrests
- Paint finish: Solid
- LED taillights
- Steering wheel: Multifunction leather steering wheel
- Illuminated makeup mirrors in the sun visors
- Non-smoking version
- Emergency call service
- Package: Seat Comfort Package
- Tire pressure monitoring system (passive)
- Wheels: Tire Mobility Set
- Keyless start system without safe locking
- electromechanical power steering
- Seat belts: Three-point automatic seat belts for the outer rear seats
- Seat covers in "Maze" fabric
- Seats: Comfort seats in the front
- Lane keeping assistant "Lane Assist"
- 12-volt power outlet in the luggage compartment
- Telephone interface with inductive charging function
- Illuminated door handle recesses
- First aid kit, warning triangle and high-visibility vest
- Warning tone and light for unfastened seat belts front and rear
- Central locking without safe locking, with remote control and 2 remote folding keys
- Airbag for driver and front passenger
- Ambient lighting
- App-Connect
- Exterior mirror housings and door handles in body color
- Vehicle tool kit
- Car2X
- Decorative inlays "Nature Cross Brushed"
- Digital Cockpit Pro, multicolor
- Parking assistance
- Electronic differential lock XDS
- Electronic stability program and electromechanical brake booster
- Electric windows, front and rear
- Pedestrian protection measures expanded
- luggage compartment cover
- Rear window heated
- Rear spoiler in car color
- "Climatronic" air conditioning system
- Front headrests
- LED reading lights at the front (2) and 2 at the rear
- LED headlights
- Dynamic headlight range control
- Fatigue detection
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Radio "Composition"
- Wheels: Alloy wheels (4) "Norfolk" 7 J x 16
- Rear bench seat undivided, backrest asymmetrically split and foldable with center armrest
- Seat belts: Three-point automatic seat belt for the middle rear seat
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Lumbar support in the front
- Start-stop system
- Bumpers in body color
- Door and side panels foam film and fabric
- Ambient lighting with logo projection
- Prepared for "We Connect" and "We Connect Plus"
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear



Extra equipment

- Anti-theft alarm system (anti-theft alarm system with interior monitoring, backup horn and tow-away protection - keyless start system with safe locking)
- Navigation system "Discover Media" including "Streaming & Internet" and voice control (25.4 cm touchscreen - 6+1 speakers - App-Connect including App-Connect Wireless for Apple CarPlay - FM and DAB+ radio reception - Multifunction camera - 4x20 watts - Dual tuner with phase diversity - 3-band sound control - RDS - MP3 playback - USB-C with Apple compatibility - Voice control - Map with 2D display - Traffic sign display - Traffic sign recognition - Telephone interface (hands-free system, Bluetooth audio))
- Package: Winter (Multifunction steering wheel in leather, heated - Gearshift knob in leather - Windscreen washer nozzles automatically heated - Front seats heated)
- "Comfort" telephone interface with inductive charging function (hands-free system)
- Air conditioning system "Air Care Climatronic" (with active combination filter, rear controls and 3-zone temperature control)
- Package: Driver assistance package including "Travel Assist" (Adaptive Cruise Control ACC "stop & go", with speed limiter - Electrically folding/adjustable exterior mirrors with memory function, separately heated - "Travel Assist", Lane Assist - Multifunction camera - "Park Assist" including parking aid - "Side Assist")
- Package: Light and Sight Package incl. High Beam Control "Light Assist" (High Beam Control "Light Assist" - Automatically Dimming Interior Mirror - Multifunction Camera - Rain Sensor)
- Lane change assistant "Side Assist" (warns the driver of vehicles that could pose a danger during lane changes by means of optical signals in the respective exterior mirror)
- Textile floor mats front and rear

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Instrument panel	Indicator light (Notruffunktion) - Specify findings - Perform diagnosis
2	Equipment	Tirefit filler - Expired - Replace
3	Sill - right side	Sill - dent(s) - Smart repair
4	Misc.	Main inspection - Expired - Replace
5	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value
6	2nd wheel set	1 alloy rim - Scratched - Replace
7	Front bumper	Front bumper - Scratch(es) - Paint
8	Rear bumper	Rear bumper - Scratch(es) - Paint
9	Door - rear left side	Door - Dent / paintcoat damage - Repair and paint
10	Door - front right side	Door - dent(s) - Repair and paint

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 20 Jul 2022	2.684,77 €



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Der montierte Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.




Damage 1: Instrument panel: Indicator light (Notruffunktion) - Specify findings - Perform diagnosis




Damage 1: Instrument panel: Indicator light (Notruffunktion) - Specify findings - Perform diagnosis



Damage 1: Instrument panel: Indicator light (Notruffunktion) - Specify findings - Perform diagnosis



Damage 1: Instrument panel: Indicator light (Notruffunktion) - Specify findings - Perform diagnosis



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Sill - right side: Sill - dent(s) - Smart repair




Damage 3: Sill - right side: Sill - dent(s) - Smart repair



Damage 4: Misc.: Main inspection - Expired - Replace



Damage 5: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value




Damage 5: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 6: 2nd wheel set: 1 alloy rim - Scratched - Replace



Damage 6: 2nd wheel set: 1 alloy rim - Scratched - Replace



Damage 6: 2nd wheel set: 1 alloy rim - Scratched - Replace



Damage 6: 2nd wheel set: 1 alloy rim - Scratched - Replace



Damage 7: Front bumper: Front bumper - Scratch(es) - Paint



Damage 7: Front bumper: Front bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 9: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




Damage 9: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 10: Door - front right side: Door - dent(s) - Repair and paint



Damage 10: Door - front right side: Door - dent(s) - Repair and paint



Damage 10: Door - front right side: Door - dent(s) - Repair and paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVVZZZCDZMW089493

Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN Golf 2.0 TDI SCR Life

Datum	KM-Stand	Beschreibung
28.10.2025	120.945	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
09.05.2023	102.753	Bremsflüssigkeit ern; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Regelwartungsdienst
25.08.2022	73.015	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
01.03.2022	38.748	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges