# KIA SPORTAGE


## Vehicle information


| | | | |
|---|---|---|---|
| Make: | **KIA** | License: | **2AQF962** |
| Gearbox: | | Body color: | |
| Model: | **SPORTAGE** | VIN: | **U5YPH812GML065360** |
| Fuel type: | | Power: | **100 kW** |
| Version: | **1.6 CRDI 136 MORE DCT** | First registration | **10/06/2021** |
| Mileage: | **139605 km** | N° of doors: | |



## Damage summary

| | |
|---|---|
| **Front** | 4 |
| **Interior** | 9 |
| **Left** | 6 |
| **Rear** | 4 |
| **Right** | 5 |
| **Roof & others** | 2 |

## Commercial pictures



















*2018/1832AP
ct applicable:
ues)

3. Vehicle fitted with eco-innovation(s): no

3.1. General code of the eco-innovation(s): -

3.2. Total CO2 emissions savings due to the eco-innovation(s)

3.2.1. NEDC savings: - g/km

3.2.2. WLTP savings: - g/km

4. All power trains, except pure electric vehicle, under Commission Regulation (EU) 2017/1151 (if applicable)

| WLTP values | CO2 emissions | Fuel consumption |
|---|---|---|
| Low: | 157 g/km | 6 l/100km |
| Medium: | 138 g/km | 5.3 l/100km |
| High: | 130 g/km | 5 l/100km |
| Extra High: | 173 g/km | 6.6 l/100km |
| Combined: | 151 g/km | 5.7 l/100km |
| Weighted, combined: | - g/km | - l/100km |

5. Pure electric vehicles and OVC hybrid electric vehicles, under Commission Regulation (EU) 2017/1151 (if applicable)

5.1. Pure electric vehicles

| | |
|---|---|
| Electric energy consumption | - Wh/km |
| Electric range | - km |
| Electric range city | |

## Tyres

**Front Left**
Summer
Aluminium
225/60/17/99/V
Goodyear
4.0 mm
**Front Right**
Summer
Aluminium
225/60/17/99/V
Goodyear
4.0 mm
**Rear Left**
Summer
Aluminium
225/60/17/99/H
Continental
5.0 mm
**Rear Right**
Summer
Aluminium
225/60/17/99/H
Continental
5.0 mm

## Checks

| | | | |
|---|---|---|---|
| Category | **Passenger Car** | Certificate of Conformity | **Yes** |
| Compressor | **N/A** | Jack | **Yes** |
| Maintenance | **OK** | Number of charging cables (normal) | **0** |
| Number of charging cables (rapid charge) | **0** | Number of keys total | **2** |
| Registration Certificate Car (BE) | **Yes** | Registration Certificate Home (BE) | **No** |
| Repair kit | **N/A** | Reset to factory settings | **No, not possible** |
| Spare wheel | **Yes** | Type of Maintenance book | **Digital maintenance** |

## VIN detail - *If the description in the language of your choice is not available, the French description is shown*

| | | |
|---|---|---|
| ABS (antiblocage des freins) | Accoudoir central arrière | Accoudoir central AV |
| AEB (freinage d'urgence autonome) | Air conditionné automatique | Airbag conducteur |
| Airbag passager | Airbags rideaux et latéraux avant | Allumage automatique des phares |
| Barres de toit | BAS (Brake Assist System) | Bluetooth |
| Caméra de récul | Capteurs de parking arrière | Clignotants intégrés dans les rétroviseurs |
| Commande à distance pour verrouillage central | Commandes audio au volant | DAW |
| DBC - Downhill Brake Control | Direction assistée | ESC - Electronic Stability Control |
| ESS (Emergency Stop Signal) | Essuie-glace avec capteur de pluie | Filtre à particules (DPF) |
| Frein de stationnement électronique | Garantie 7 ans/150.000 km | GPS+TomTom Live+Apple Car Play+DAB |
| HAC (Hill Assist Control) | Haut-parleurs (6) | HBA - High Beam Assist (Assistant de Feux de Route) |
| Intérieur tissu | ISG - Idle Stop & Go | JAV 17'' + 225/60 |
| Limitateur de vitesse | LKA - Lane Keep Assist (Assistance au Suivi de Voie) | Pare-chocs en couleur carrosserie |
| Peinture unie | Phares antibrouillard avant | Phares arrière de type LED |
| Phares de jour de type LED | Poignées coul.carrosserie+chrome | Pommeau de vitesse en cuir |
| Prise 12V à l'avant et à l'arrière | Prise de chargement USB à l'arrière | Régulateur de vitesse adaptatif |
| Rétroviseur intérieur électrochromatique | Rétroviseurs chauffants | Rétroviseurs extérieurs électriques |
| Rétroviseurs extérieurs en couleur carrosserie | Rétroviseurs rabattables électriquement | Roue de réserve temporaire |
| Siège conducteur avec réglage lombaire | Siège conducteur réglable en hauteur | Siège passager réglable en hauteur |
| TSA - Trailer Stability Assist | Verrouillage central des portes | Vitres électriques AR |
| Vitres électriques AV | Vitres lat. AR+lunette AR en verre teinté foncé | Volant en cuir |
| Volant réglable en hauteur et en profondeur | VSM (Vehicle Stability Management) | |

### Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.