Volkswagen

1.4 EHYBRID STYLE BUSINESS DSG

VIN: WVWZZZCD1PW310598



Description

Registration number 2DWT724	**First registration date** 18/07/2023	**Odometer** 46020 km
Color Deep Black Nacré	**Model year** 2020	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 1395	**Gearbox type** Automatic	**Engine type** Plug-in Hybrid
Number of gears 6	**Drivetrain** Front Wheel Drive (FWD)	**Max power** 150 KW

Vehicle Equipments

Rain-sensitive wipers	Automatic headlights	Towing
Alloy wheel rims	Climate control	Cruise control
Electrically foldable door mirrors	SATNAV	Park Assist

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 30/10/2026	**Inspection approval date** 02/11/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Rim / Front Right Rim/Tyre diameter : 16 "	Scratched	Acceptable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.





002	Rim / Back Right Rim/Tyre diameter : 16 "	Scratched	Acceptable






003	Rim / Back Left Rim/Tyre diameter : 16 "	Scratched	Acceptable




004	Door / Back Left	Scratched	Acceptable

005	Bonnet / -	Chip	Painting

006	Spoiler / Front Painted : Yes	Dent	Repair








007	Bumper / Front Painted : Yes	Scratched	Smart repair

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.





008	Roof / - [1]	Chip	Painting

009	Bumper / Back Painted : Yes	Scratched	Acceptable





[1] Le toit est rempli de petits éclats

Loose Items

- [x] Slow charging cable (Type 2, Mode 2)
- [x] Quick charging cable (Type 2, Mode 3)
- [x] Conformity certificate
- [x] Registration certificate
- [x] Registration certificate owner
- [x] Card key
- [x] Spare Key
- [x] User manual
- [x] Rear parcel shelf

Main set of tyres

Front Left	PIRELLI	205/55/16 All-season	4 mm
Front Right	PIRELLI	205/55/16 All-season	4 mm
Back Left	PIRELLI	205/55/16 All-season	8 mm
Back Right	PIRELLI	205/55/16 All-season	8 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures



Front left



Rear left



Boot opened




Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer



Navigation



Spare Tyre



Cable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Cable




Vin



Other



Other



Other



Other



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Back Right / Scratched



Rim / Back Right / Scratched



Rim / Back Left / Scratched



Rim / Back Left / Scratched



Door / Back Left / Scratched



Door / Back Left / Scratched




Bonnet / - / Chip

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bonnet / - / Chip



Bonnet / - / Chip



Spoiler / Front / Dent



Spoiler / Front / Dent



Bumper / Front / Scratched




Bumper / Front / Scratched




Bumper / Front / Scratched




Roof / - / Chip



Roof / - / Chip



Roof / - / Chip



Roof / - / Chip



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.