DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	WBA11EE02 05325126	Mileage	62 341 km	Engine (Fuel) Type	Petrol
Licence Plate	2HAJ503	Registration date	13/05/2025	Engine size	1499
Brand	BMW	Fuel level	-	Transmission	Automatic
Model	X1-2022	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Noir		

Inspection Details

Inspection date	04/11/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique




Other technical information

Emergency compressor kit	✓	Service manual holder	✓
Refill emergency kit	✓	User manual	✓
Rear parcel shelf	✓	Adapter USB	✓

Options / Equipment

Tyres

Michelin 225/55/18 Y Summer 5.0 mm		Michelin 225/55/18 Y Summer 5.0 mm	
Michelin 225/55/18 Y Summer 5.0 mm		Michelin 225/55/18 Y Summer 5.0 mm	





Damages

1



Part	Interior tailgate lining
Position	-
Damages	Scratched
Severity	-
Repair mode	Replace

2



Part	Service
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

3



Part	Bumper
Position	Front left
Damages	Dented
Severity	-
Repair mode	For info

4




Part	Bumper grille
Position	Front left
Damages	Broken
Severity	-
Repair mode	Replace

5



Part	Windscreen with camera
Position	-
Damages	Stone impact
Severity	-
Repair mode	Replace

6



Part	Door
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	For info

7



Part	Spoiler
Position	Back
Damages	Dent & Chips
Severity	-
Repair mode	Repair

8



Part	Bumper
Position	Back
Damages	Dent & Chips
Severity	-
Repair mode	Repair

9



Part	Reflector
Position	Back right
Damages	Broken
Severity	-
Repair mode	Replace

10



Part	Door
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

11



Part	Special rim 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Smart Repair

12



Part	Door
Position	Front right
Damages	Dented
Severity	-
Repair mode	For info

13



Part	Bonnet
Position	-
Damages	Dented
Severity	-
Repair mode	Smart Repair