MACADAM










Peugeot 208: N921JR

Vinnumber:	**VR3UPHMHDM5853034**	Versionname:	**208 1.2 Puretech 55kW Active**
First Registrationdate:	**29/10/2021**	Fiscalpower:	
Expertise Mileage:	**75558**	Power Kw:	**55**
Bodytype:		Body colour	**Noir Perla Nera metaallak**
Gearbox:	**MAN 5 VIT**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Steel**
Fueltype:	**Petrol**	Parking lot	**399**
Number of seats	**5**		
Type of rims (mounted)	**Steel**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**
Manual climate control	
Radio multimedia	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	185 / 65 / 15 / 88 / T / Steel	6,2 mm	Bridgestone	Summer
	Right	185 / 65 / 15 / 88 / T / Steel	6,2 mm	Bridgestone	Summer
Rear	Left	185 / 65 / 15 / 88 / T / Steel	3,8 mm	Bridgestone	Summer
	Right	185 / 65 / 15 / 88 / T / Steel	3,2 mm	Bridgestone	Summer

Assistance equipment

Service, Maintenance, Execute



Door FL, Scratch(es), Repair and paint (complete)




Door RL, Scratch(es), Repair and paint (complete)




Outer sill L, Scratch(es), Repair and paint (complete)




Wing RL, Scratch(es), Repair and paint (complete)






Outside rear-view mirror housing L, Scratch(es), Replace and paint






Bonnet, Chemical polution, Repair and paint (complete)




Bumper F, Scratch(es), Polish




Door RR, Scratch(es), Polish






Wing RR, Dent(s) and scratch(es), Repair and paint (complete)








Door FR, Scratch(es), Repair and paint (complete)




Shutter / cover R, Missing, Replace





Bumper R, Scratch(es), Repair and paint (complete)







Roof, Dent(s) and scratch(es), Repair and paint (complete)






Onderhoudshistorie van: VR3UPHMHDM5853034

ALPHABET

Kenteken	N921JR
Merk Model	Peugeot 208 1.2 Puretech 55kW Active
Brandstofsoort	Benzine
Datum deel1	10/29/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
1/27/26	63,108	Vervanging band
9/30/25	56,925	APK
8/12/24	41,538	Uitlijnen voor en achterwielen
8/12/24	41,538	Vervanging band
8/2/24	41,438	Bougie
8/2/24	41,438	Luchtfilter
8/2/24	41,438	Onderhoudsbeurt
8/2/24	41,438	Remschijf + blokken voor
8/2/24	41,438	Ruitenwisserblad(en) voorzijde
10/20/23	26,860	Onderhoudsbeurt
10/20/23	26,860	Ruitenwisserblad(en) voorzijde
10/28/22	17,243	Onderhoudsbeurt