



## Peugeot 3008:

Vinnumber:	<b>VF3M4DGZUMS201596</b>	Versionname:	
First Registrationdate:	<b>27/09/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>110633</b>	Power Kw:	
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>1204</b>
Fueltype:	<b>Hybrid Petrol</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

## Options

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	<b>Tow bar removable</b>
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining semi-artificial leather</b>		
Type of climate control:	<b>Autom climate control</b>		

## Limited Technical Inspection

## Tyres

<b>225/55/18/102 V</b>				
Winter tyres:	Fr.L.	<b>Vredestein: 4 mm</b>	Fr.R.	<b>Vredestein: 4 mm</b>
	Re.L.	<b>Vredestein: 4 mm</b>	Re.R.	<b>Vredestein: 4 mm</b>
Tyre profile depth FL:				<b>4.0</b>
Tyre profile depth FR:				<b>4.0</b>
Tyre profile depth RL:				<b>4.0</b>
Tyre profile depth RR:				<b>4.0</b>
Tyre size FL:				<b>225/55 R 18 102 V</b>
Tyre size FR:				<b>225/55 R 18 102 V</b>
Tyre size RL:				<b>225/55 R 18 102 V</b>
Tyre size RR:				<b>225/55 R 18 102 V</b>
Tyre type FL:				<b>Winter</b>
Tyre type FR:				<b>Winter</b>
Tyre type RL:				<b>Winter</b>
Tyre type RR:				<b>Winter</b>
Tyre make FL:				<b>2480</b>
Tyre make FR:				<b>2480</b>
Tyre make RL:				<b>2480</b>
Tyre make RR:				<b>2480</b>

## Assistance equipment

Number of charging cables (normal):	<b>0</b>
Number of charging cables (rapid charge):	<b>1</b>

Total cost ex VAT:	<b>299,68</b>
Seat cover FL, Worn, Acceptable:	<b>0,00</b>



Door FL, Dent(s), Paintless dent repair 95,47



Charging cable (normal), Missing, Check 0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Wing trim RR, Scratch(es), Acceptable 0,00

