SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Bas Vaasen

2-GEX-161

2-GEX-161 · Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / · 4 November 2026 · Zaventem Brussel

Specifications

License Plate Number	2-GEX-161
Manufacturer	TOYOTA
Model	Corolla Cross
Model Versions	Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT /
Body Type	5 door hatchback
Color	Grey
Paint Type	Metallic
Production Year	2024
KW	103
Fuel Type	Hybrid Gasoline

VIN	JTNADADB70J024344
Cylinder Capacity	1.798 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	20-11-2024
First Registration	20-11-2024
Odometer	70.628 Km
Numer Of Keys	2
Interior	Black – Cloth
Number Headrests	5

Images

































Accessories

ABS	Cruise control
Airbags	Electric rear windows
Alloy wheels	Electric windows front
ASR	Electrically adjustable exterior mirrors
Audio System	Leather steering wheel
Automatic air conditioning	Parking sensors
Bluetooth car kit	Rear view camera
Central door locking	Roller cover / parcel shelf
Centre armrest	Steering wheel multifunction

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 mm	UniRoyal	215 mm	60 mm	17 inch	All Season
Rear Left	5 mm	UniRoyal	215 mm	60 mm	17 inch	All Season
Front Right	2 mm	UniRoyal	215 mm	60 mm	17 inch	All Season
Rear Right	5 mm	UniRoyal	215 mm	60 mm	17 inch	All Season
Spare Tire Type	Homecomer					

Damages





Damage Part	Damage Type	Notes	Repair Type	Acceptable
Overfender	Small scratch(es)	LV & RV	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Dent(s)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Small scratch(es)	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No








Damage Part	Damage Type	Repair Type	Acceptable
Rear	Small scratch(es)	Polish	No