



Ford Mustang: L986SN

Vinnumber:	WF0TK1EM9MMA22411	Versionname:	Mustang Mach-E 190kW/ 75,7kWh RWD automaat (NEDC)
First Registrationdate:	23/07/2021	Fiscalpower:	
Expertise Mileage:	176243	Power Kw:	190
Bodytype:		Body colour	Premium Metaallak: Carbonized Grey
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	412
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining leather
GPS		Rear parking sensors
Autom climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 60 / 18 / 104 / W / Aluminium	7,0 mm	Hankook	Summer
	Right	225 / 60 / 18 / 104 / W / Aluminium	7,0 mm	Hankook	Summer
Rear	Left	225 / 60 / 18 / 104 / W / Aluminium	6,8 mm	Hankook	Summer
	Right	225 / 60 / 18 / 104 / W / Aluminium	7,0 mm	Hankook	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Door FL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Chemical polution, Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Hail damage, Paintless dent repair (hail)



Kenteken	L986SN
Merk Model	Ford Mustang Mach-E 198kW/ 75,7kWh RWD automaat
Brandstofsoort	Elektrisch
Datum deel1	23-07-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
23-12-25	158.892	Reparatie band(en)
09-10-25	152.738	Handrem mechanisme
09-10-25	152.738	Remklauw(en) achterzijde
21-07-25	144.340	APK
18-07-24	107.368	Vervanging band
05-03-24	93.844	Airco controle
05-03-24	93.844	Airco reinigen
05-03-24	93.844	Airo vulling
05-03-24	93.844	Onderhoudsbeurt
05-03-24	93.844	Remvloeistof
05-03-24	93.844	Sleutelbatterij
24-03-23	60.309	Onderhoudsbeurt
24-03-23	60.309	Ruitenwisserblad(en) voorzijde
15-11-22	47.354	Afstandsbediening
15-11-22	47.354	Navigatiesysteem
09-09-22	40.507	Reparatie band(en)
19-05-22	29.210	Onderhoudsbeurt
03-11-21	12.613	Reparatie band(en)