

Mercedes

MERCEDES-BENZ EQA (BM 243)(02.2021->) EQA 350 4MATIC (243.712) MOTEUR ÉLECTRIQUE 215 KW 5 PORTES

VIN: W1N2437121J036342



Description

Registration number	Registration date	Odometer
	28/03/2022	86822 km
Color	Year	Upholstery
KOSMOSBLACK - MET.	2021	-
Number of doors	Number of seats	Generation
5	5	-
Gearbox type	Engine type	Number of gears
Automatic	Electric	1
Max power		
215 KW		

Vehicle Equipments

Standard

Seat Comfort package	roof liner black	light alloy rims
liftgate with automatic opening and closing system	charging system alternating current (AC)	center armrest rear
airbag driver side/passenger side	lap airbag front (Pelvisbag)	kneebag driver side
sidebag front	lumbar support seat front left and right, electrically adjustable	rear seat backrest split/folding (40:20:40)
transmission for electric vehicle	reversing camera	body: 5-door
voice-command system extended functions (MBUX)	center console front with roll-up cover / tray	Electronic Stability Control (ESP)
tire pressure control system	charging cable for public charging pillars (mode 3)	radio reception digital (DAB)
power steering	wheelbase 2729 mm	windshield wiper with rain sensor
baggage net at front seatback	Light-alloy rims	tire repair kit
window lifter electric front + rear	Mercedes-Benz emergency call system	Type of drive: all-wheel drive
communication module (LTE) preparation Mercedes me connect	electric motor 215 kW	Cargo space package
Light and Vision package	tire 235/55 R18 ...H	power outlet (12V outlet) in trunk/load space
headlight LED High Performance	acoustic pedestrian protection (external sound)	loading edge protector (chrome-plated)
preparation Remote + navigation services	cruise control (cruise control)	exterior mirror electrically adjustable and heated, both
beverage holder front (dual)	Isofix mounts for child seat at rear seat	comfort suspension lowered (Agility Control)
head airbag system (Sideguard)	antilock braking system (ABS)	driver assistance system: active lane-keeping assistant
driver assistance system: Multi-Sense (driving mode switch)	driver assistance system: speed limit display	driver assistance system: high-beam assistant
driver assistance system: traffic information system Live traffic	navigation system: hard disk navigation	infotainment system: Remote & Charging Services Premium
multimedia system MBUX (digital multimedia system)	Touchpad (center console)	steering wheel (Sport) with multiple function
ambient lighting		

Optional

airbag passenger side deactivatable	change year with code 052 (11/2)	change year with code 802
roof rails high-gloss Shadow-Line	multi-functional camera	Inductive charging tray for mobile devices
automatic air-conditioning system	charging cable (7,0 m) with three-pin plug (mode 2)	Design and equipment line AMG Line
entry rails (stainless steel) illuminated	front skirt	rear apron
interior equipment trim parts backlit	stainless steel pedals Sports design	floor mats velours
seat covers/upholstery: synthetic leather Artico / Dinamica	sports seats front	steering wheel (leather nappa, levelled bottom)
instrument cluster digital (virtual cockpit)	entry illumination with logo projection feature	fire extinguisher
refrigerant R 1234 YF	Light-alloy rims	keyless door release
central locking system with remote control	media display	Equipment package: Advanced Plus
Keyless-Go package	mirror package	exterior mirror electrically folding
side/rear-view mirrors with automatic dimming	Parking package	exterior mirror with blind-spot assistant
sound system	Night package	exterior mirror black painted
side window rear and rear window darkened	sun visors with mirror (illuminated)	metallic paintwork
charging socket COMBO 2 / type 2	preparation car sharing	seat heating front
Smartphone integrated	driver assistance system: active brake assistant	driver assistance system: parking assistant (Active Park Assist)
charging system direct current (DC)		

Statement details

Inspection loc

Statement date
16/07/2026



Inspection approval date
17/07/2026


Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Personal Data / -	None	Cleaning
			
002	Roof / - ¹ Sunroof : No	Paint etching	Polishing
			
003	Bonnet / -	Paint etching	Polishing
			
004	Door sill / Front Left	Dent	Acceptable
			
005	Roof post A/B/C / Left	Dent	Smart repair

		
006	Tailgate / Boot door / -	Smart repair
		
007	Seat / Front Right Trim material : Fabric	Cleaning
		
008	Bumper / Front Painted : Yes	Smart repair
		
009	Bumper moulding / Front Left Painted : No / Chromed : No	Painting
		
010	Bumper moulding / Front Left Painted : Yes	Acceptable
		

¹ + deukje aanvaardbaar

Loose Items

- ☒ Rear parcel shelf
- ☒ Tyre repair kit complete
- ☐ Document holder
- ☒ Registration certificate owner
- ☐ Toolkit
- ☐ Jack handle crank
- ☒ Slow charging cable (Type 2, Mode 2)
- ☒ Charging cable bag
- ☒ Spare Key
- ☐ Service book
- ☐ Towing hook
- ☐ Cargo net
- ☐ Remote key
- ☐ Security Kit
- ☒ Triangle
- ☐ Warranty booklet
- ☐ Hook /Hicth ball
- ☐ Card key
- ☐ Locking wheel nuts key
- ☒ Conformity certificate
- ☐ Spare wheel tyre
- ☒ Quick charging cable (Type 2, Mode 3)
- ☒ Safety vest
- ☐ Remote control
- ☒ Compressor tyre repair kit
- ☒ First aid kit
- ☐ User manual
- ☐ Jack
- ☐ Load cover
- ☒ Refill tyre repair kit
- ☒ Registration certificate
- ☐ Satellite navigation
- ☐ In-car tools
- ☐ Locking wheel nut

Main set of tyres

Front Left	PIRELLI	235 / 55 / 18 / All	5 mm
Front Right	PIRELLI	235 / 55 / 18 / All	5 mm
Back Left	MICHELIN	235 / 55 / 18 / All	3 mm
Back Right	MICHELIN	235 / 55 / 18 / All	3 mm

Comments

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat




Front passenger compartment



Front right




Odometer



Navigation



Spare Tyre




Cable



Cable




Vin



Other



Other




Other



Other



Personal Data / - / None



Personal Data / - / None




Roof / - / Paint etching



Roof / - / Paint etching




Roof / - / Paint etching




Bonnet / - / Paint etching



Bonnet / - / Paint etching



Door sill / Front Left / Dent



Roof post A/B/C / Left / Dent



Roof post A/B/C / Left / Dent



Tailgate / Boot door / - / Dent




Tailgate / Boot door / - / Dent



Seat / Front Right / Dirty



Bumper / Front / Scuff



Bumper / Front / Scuff



Bumper / Front / Scuff



Bumper moulding / Front Left / Scuff



Bumper moulding / Front Left / Scuff



Bumper moulding / Front Left / Scratched



Bumper moulding / Front Left / Scratched

Appendices : SOH Report

 POWERED BY AVILOG

OEM SoH numérisé*



SoHSCAN



INFORMATIONS SUR LE VÉHICULE

Marque: Mercedes-Benz
Modèle: EQA - 66,5 kWh
VIN: W1N2437121J036342
Kilométrage: 86 823km
SoH numérisé*: 96%



INFORMATIONS SUR LA LECTURE

Date: 16/07/2026
Exécuté par: DEKRA Belgium NV/SA

PROTOCOLE D'EXÉCUTION

09:20:10 SoHSCAN démarré
09:20:23 Démarrage de l'acquisition des données
09:22:25 Acquisition des données terminée
09:22:40 SoHSCAN terminé

* Pour obtenir une évaluation complète de la sécurité et de la valeur de la batterie, tenez compte des éléments suivants :

1. Les anomalies et dysfonctionnements éventuels de la batterie et des cellules ne sont pas révélés par le SoHSCAN. Elles peuvent être facilement détectées, jusqu'au niveau de la cellule, à l'aide du test Flash AVILOG.
2. L'état de santé (SoH) numérisé (lecture) par le fabricant (OEM) de la batterie d'entraînement est le SoH supposé par le système de gestion de la batterie (BMS). Il peut s'écarter considérablement du véritable SoH, et AVILOG n'assume aucune responsabilité quant à son exactitude.
3. Le SoH réel peut être déterminé avec précision à l'aide du test PREMIUM AVILOG.

