



Mercedes-Benz CLA 250: Z557DB

Vinnumber:	W1K5M8FB8RN475371	Versionname:	CLA250e 1.3 160kW PHEV AMG Line shooting brake DCT
First Registrationdate:	22/03/2024	Fiscalpower:	
Expertise Mileage:	102834	Power Kw:	120
Bodytype:		Body colour	Cosmoszwart metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Hybrid Petrol	Parking lot	1151
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining semi-leather
GPS		Lining Alcantara
Autom climate control		Sun Roof electric
Radio multimedia		Rear parking sensors
		Hook
		Rear view camera

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 40 / 19 / 93 / W / Aluminium	4,8 mm	Bridgestone	Summer
	Right	225 / 40 / 19 / 93 / W / Aluminium	4,4 mm	Bridgestone	Summer
Rear	Left	225 / 40 / 19 / 93 / W / Aluminium	4,0 mm	Bridgestone	Summer
	Right	225 / 40 / 19 / 93 / W / Aluminium	4,8 mm	Bridgestone	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Door FL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)




Wing RL, Scratch(es), Repair and paint (complete)



Roof pillar L, Scratch(es), Polish



Roof pillar R, Dent(s), Repair and paint (complete)



Tow bar (fixed), Deformed / Strained, Replace



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Kenteken	Z557DB
Merk Model	Mercedes-Benz CLA250e 1.3 160kW PHEV AMG Line shooting brake DCT
Brandstofsoort	Benzine
Datum deel1	22-03-24

Datum reparatie	Kilometerstand	Reparatie omschrijving
26-05-26	97.397	Onderhoudsbeurt
27-11-25	74.975	Bougie
27-11-25	74.975	Luchtfilter
27-11-25	74.975	Onderhoudsbeurt
27-11-25	74.975	Remvloeistof
27-11-25	74.975	Ruitenwischerblad(en) voorzijde
07-06-25	52.841	Vervanging band
03-06-25	52.387	Onderhoudsbeurt
07-04-25	44.274	Sleutelbatterij
14-11-24	24.714	Onderhoudsbeurt
14-11-24	24.714	Ruitenwischerblad(en) voorzijde
28-06-24	7.766	Vervanging band