



CITROËN C3: 4423-LZF

Vinnumber:	VF75XYHTUNT570302	Versionname:	Citroen BlueHDi 75KW (100CV) S&S Live Pack berlina con portón 75kW 5P manual
First Registrationdate:	14/07/2022	Fiscalpower:	
Expertise Mileage:	205872	Power Kw:	
Bodytype:	Berline	Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Steel		
Certificate of Conformity	No		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	1	Radio
Number keys remote	1	Luggage cover
Windows electric F		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of climate control	Manual climate control	

Tyres

185/65/15/88 H				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				185/65 R 15 88 H
Tyre size FR				185/65 R 15 88 H
Tyre size RL				185/65 R 15 88 H
Tyre size RR				185/65 R 15 88 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Boot lid covering R, Scratch(es), Replace



Interior, Dirty, Cleaning



Interior, Damaged, Replace



Malfunction indicator, Blinking, Check



User's manual, Missing, Repair/replace (lump sum)



Service book, Missing, Repair/replace (lump sum)



MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Wheel cover FL, Scratch(es), Replace



Door RL, Dent(s), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)




Wheel cover RL, Scratch(es), Replace



Bumper F, Scratch(es), Repair and paint (complete)



Wing trim RR, Scratch(es), Paint




Wheel cover RR, Scratch(es), Replace



Door RR, Scratch(es), Repair and paint (complete)



Wheel cover FR, Scratch(es), Replace




Headlight R, Scratch(es), Polish



Bumper R, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Dent(s), Acceptable



Tyres, No damage, Check



