



Peugeot 208: N107RH

Vinnumber:	VR3UHZKXZMT112945	Versionname:	e-208 50kWh 100kW Active Pack automaat
First Registrationdate:	13/12/2021	Fiscalpower:	
Expertise Mileage:	164041	Power Kw:	100
Bodytype:		Body colour	Blanc Banquise standaardlak
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	518
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Rear parking sensors
GPS		
Autom climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 87 / H / Aluminium	5,1 mm	Continental	Summer
	Right	195 / 55 / 16 / 87 / H / Aluminium	5,2 mm	Continental	Summer
Rear	Left	195 / 55 / 16 / 87 / H / Aluminium	6,3 mm	Continental	Summer
	Right	195 / 55 / 16 / 87 / H / Aluminium	6,2 mm	Continental	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Interior, Stain, Cleaning



Outside rear-view mirror housing L, Scratch(es), Polish



Door FL, Dent(s) and scratch(es), Repair and paint (complete)





Bumper F, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Bumper R, Bad repair, Repair and paint (complete)



Kenteken	N107RH
Merk Model	Peugeot e-208 50kWh 100kW Active Pack automaat
Brandstofsoort	Elektrisch
Datum deel1	13-12-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
02-07-26	163.120	Onderhoudsbeurt
02-07-26	163.120	Ruitenwischerblad(en) achterzijde
02-12-25	138.875	APK
02-09-25	127.347	Onderhoudsbeurt
02-09-25	127.347	Remvloeistof
02-09-25	127.347	Tankklep
02-09-25	127.347	Vervanging band
24-04-25	113.939	Reparatie band(en)
11-12-24	97.904	Onderhoudsbeurt
11-12-24	97.904	Ruitenwischerblad(en) voorzijde
08-11-24	94.747	Vervanging band
08-03-24	71.922	Onderhoudsbeurt
08-03-24	71.922	Remvloeistof
25-01-24	66.794	Vervanging band
20-07-23	48.850	Onderhoudsbeurt
27-09-22	24.057	Onderhoudsbeurt
08-06-22	16.315	Onderhoudsbeurt