SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Bas Vaasen

# 2-GEX-160

2-GEX-160 · Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / · 4 November 2026 · Zaventem Brussel

## Specifications

| | |
|---|---|
| License Plate Number | 2-GEX-160 |
| Manufacturer | TOYOTA |
| Model | Corolla Cross |
| Model Versions | Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / |
| Body Type | 5 door hatchback |
| Color | Grey |
| Paint Type | Metallic |
| Production Year | 2024 |
| KW | 103 |
| Fuel Type | Hybrid Gasoline |

| | |
|---|---|
| VIN | JTNADADB50J024360 |
| Cylinder Capacity | 1.798 cm3 |
| Transmission Type | Automatisch geschakelde Transmissie |
| First Admission | 20-11-2024 |
| First Registration | 20-11-2024 |
| Odometer | 47.400 Km |
| Numer Of Keys | 2 |
| Interior | Black – Cloth |
| Number Headrests | 5 |

## Images
































## Accessories

| | |
|---|---|
| ABS | Electric rear windows |
| Airbags | Electric windows front |
| Alloy wheels | Electrically adjustable exterior mirrors |
| ASR | Leather steering wheel |
| Audio System | Navigation system |
| Automatic air conditioning | Parking sensors |
| Bluetooth car kit | Rear view camera |
| Central door locking | Roller cover / parcel shelf |
| Centre armrest | Steering wheel multifunction |
| Cruise control | |

## Condition

| | | | |
|---|---|---|---|
| Condition exterior | Adequate | Last Maintenance | Unknown |
| Condition interior | Adequate | Previous Repairs | Unknown |

## Tire Specifications

| Tire | Profile | Brand | Width | Aspect Ratio | Radial | Type |
|---|---|---|---|---|---|---|
| Front Left | 3 mm | UniRoyal | 215 mm | 60 mm | 17 inch | All Season |
| Rear Left | 5 mm | UniRoyal | 215 mm | 60 mm | 17 inch | All Season |
| Front Right | 3 mm | UniRoyal | 215 mm | 60 mm | 17 inch | All Season |
| Rear Right | 5 mm | UniRoyal | 215 mm | 60 mm | 17 inch | All Season |
| Spare Tire Type | Homecomer | | | | | |

## Damages




| Damage Part | Damage Type | Repair Type | Acceptable |
| --- | --- | --- | --- |
| Interior | Stains & dirt | Cleaning | No |




| Damage Part | Damage Type | Repair Type | Acceptable |
| --- | --- | --- | --- |
| Bumper – Front | Stonechipping | Acceptable | Yes |






| Damage Part | Damage Type | Notes | Repair Type | Acceptable |
| --- | --- | --- | --- | --- |
| Bumper – Rear | Previous Repair | kleurverschil | Spray | No |