



Mercedes A-Klasse (UKL): 2CMZ731

Vinnumber:	W1K3F8EB3PV151406	Versionname:	A180 Business Solution Essential 1.3i 136pk/cv 5p
First Registrationdate:	22/09/2022	Fiscalpower:	
Expertise Mileage:	108627	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	NOT OK		
Maintenance	0.0		
Maintenance	B		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/60/18/92 V				
Summer tyres:	Fr.L.	Pirelli: 5,1 mm	Fr.R.	Pirelli: 4,5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL				5.1
Tyre profile depth FR				4.5
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/60 R 18 92 V
Tyre size FR				205/60 R 18 92 V
Tyre size RL				205/60 R 18 92 V
Tyre size RR				205/60 R 18 92 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover FL, Worn, Acceptable



Floor covering FL, Burned, Smart repair



Seat cover FR, Stain, Cleaning



Service, Maintenance, Check



Bumper F, Scratch(es), Spot repair



Bonnet, Dent(s) and scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Wing RL, Dent(s) and scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Roof pillar R, Dent(s), Acceptable



Door RR, Dent(s), Acceptable



Door FR, Scratch(es), Acceptable



Kenteken	2CMZ731
Merk Model	Mercedes A180 Business Solution Essential 1.3i 136pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	9/22/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/2/26	96,380	halogeenlamp	Vervangen
7/16/25	84,408	diagnose	Uitvoeren
7/9/25	83,522	bougie	Vervangen
7/9/25	83,522	klein materiaal	
7/9/25	83,522	luchtfILTER	Vervangen
7/9/25	83,522	mercedes assyst a	Uitvoeren
7/9/25	83,522	ruitenswisserrubber vooraan	Vervangen
7/3/25	83,522	ruitenswisserrubber vooraan	Vervangen
8/29/24	59,706	klein materiaal	Uitvoeren
8/29/24	59,706	mercedes assyst b	Uitvoeren
8/29/24	59,706	remvloeistof	Vervangen
8/29/24	59,706	ruitenswisserrubber vooraan	Vervangen
10/30/23	29,909	klein materiaal	Uitvoeren
10/30/23	29,909	mercedes assyst b	Uitvoeren
10/30/23	29,909	ruitenswisserrubber vooraan	Vervangen
4/6/23	11,164	universele lampen	Vervangen