



Tesla Model 3:

Vinnumber:	LRW3E7FAXMC237720	Versionname:	
First Registrationdate:	10/06/2021	Fiscalpower:	
Expertise Mileage:	114097	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3425
Fueltype:	Electric		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Panoramic roof	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

235/45/18/92 H				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/45 R 18 92 H
Tyre size FR				235/45 R 18 92 H
Tyre size RL				235/45 R 18 92 H
Tyre size RR				235/45 R 18 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Total cost ex VAT	1811,08
Bumper F, Scratch(es), Repair and paint (complete)	296,58



Windscreen, Scratch(es), Polish 0,00



Alloy rim RL, Scratch(es), Acceptable 0,00



Door RL, Bad repair, Check 0,00



Alloy rim FL, Scratch(es), Repair and paint (complete) 133,03



Charging cable (normal), Missing, Check 0,00



Bumper R, Scratch(es), Acceptable 0,00



Tailgate / Boot, Dent(s), Acceptable 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03



Door RR, Dent(s) and scratch(es), Repair and paint (complete) 624,32



Wing RR, Dent(s) and scratch(es), Repair and paint (complete) 491,09



Alloy rim RR, Scratch(es), Repair and paint (complete)

133,03

