

Condition Report

DEKRA/ /20260507

Ordered By

Ordered By

Vehicle

License Plate		Contract Number		Bodywork Type	SUV	Transmission	Automatic
Brand	SEAT	VIN	VSSZZZ5F0P6560234	Drive Wheel	Front-wheel-drive	First Registration	2023.06.27
Model	Ateca	Year Built	2023	Color	White	Fuel Type	Petrol
Label	-	Capacity	1.498 cm3	Power	110 kW	Mileage	128.079 km
MOT	2027.06.27						

Equipment

- Automatic air conditioning / digital
- Electrically adjustable front and rear windows
- Multifunction steering wheel
- ESP / DSC
- ASD / EDS / ASR

Documents

- Original Key
- Registration Book
- Vehicle Manual
- Spare tire

Wheels

Position	Rim Type	Dimensions	Thread Depth
FL	Könnyűfém	215/55R17	3.00
FR	Könnyűfém	215/55R17	3.00
RL	Könnyűfém	215/55R17	3.00
RR	Könnyűfém	215/55R17	3.00
SP	Acél	125/70R18	3.00

Paint Thickness [µm]


Part	Left Value	Right Value
Front mudguard	119	118
Engine cover	119	0
Front door	123	121
Rear door	124	126
Roof	112	0
Rear mudguard	124	124
Luggage compartment lid / Rear door	101	0

Last Service

Type	Date	KM
------	------	----

Standard Images





Special Notes

A gépjármű poros.

Inspection Details

Inspection Place		Inspection Person		Inspection Date	2026.05.05
------------------	--	-------------------	--	-----------------	------------

This condition report was prepared by an expert of DEKRA-Expert Kft.

The vehicle inspection was carried out by external visual examination. No test drive was performed and no parts were disassembled during the inspection.

The calculation of unacceptable defects and deficiencies was prepared using data from the Audatex and Eurotax calculation programs.

The expert inspection was carried out in accordance with DEKRA regulations, applying the client's guidelines regarding acceptable and unacceptable defects and deficiencies for returned vehicles.