




1.0i Ecoboost Hybrid 125pk Aut Titanium X · 2 June 2026 · Schiphol

Specifications

		Cylinder Capacity	999 ^{cm³}
Manufacturer	FORD	Transmission Type	Handmatig geschakelde transmissie6
Model	Puma	MOT	15-09-2026
Model Versions	1.0i Ecoboost Hybrid 125pk Aut Titanium X	First Admission	15-09-2022
Body Type	SUV	First Registration	15-09-2022
Color	White	License Plate 1a Available	
Paint Type	Matte	VAT/Marge	BTW
BPM	€ 3.791	Odometer	199.198 ^{Km}
Production Year	2022	Numer Of Keys	2
KW	91	Interior	Darkgrey - Cloth
Fuel Type	Gasoline	Number Headrests	5
VIN	WF02XXERK2NU42174		

Images





Accessories

ABS

Airbags

Alloy wheels

ASR

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Dimming interior mirror

Electric rear windows

Electric windows front

Electrically adjustable & heated exterior mirrors

ESP

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs

Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 ^{mm}	Vredestein Quatrac	215 ^{mm}	55 ^{mm}	17 ^{inch}	All Season
Rear Left	7 ^{mm}	Vredestein Quatrac	215 ^{mm}	55 ^{mm}	17 ^{inch}	All Season
Front Right	6 ^{mm}	Vredestein Quatrac	215 ^{mm}	55 ^{mm}	17 ^{inch}	All Season
Rear Right	7 ^{mm}	Vredestein Quatrac	215 ^{mm}	55 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Homecomer					
Spare Tire Profile	5 ^{mm}					

Damages



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Frontdoor - Left	Small scratch(es)	Deurgreep lakbeschadiging	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Left	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper - Rear	Small dent(s)	Middenbalk	Plastic Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
spoiler RB	Small scratch(es)	Acceptable	Yes



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Right

Small dent(s)

Acceptable

Yes



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Bumper - Front

Scratch(es)

& herplaatsen

Panelbeating & Spray

No



Damage Part

Damage Type

Repair Type



Acceptable

Hood

Small dent(s)

Acceptable

Yes



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Other

Scratch(es)

Velg LV / RV krassen

Rim repair

No