

INSPECTION REPORT


End of contract

GENERAL INFO

File	315402
License plate	1XHQ262
Vehicle identification number	WAUZZZF38L1047064
Dossier	2019276180
Make	Audi Q3 SB 35 TFSI S Line
Mileage	50433
First registration	08/01/2020
client availability date	18/06/2026
inspectionDate	29/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
187	Wing Rear Right / Trim / Replace	N
190	Door Rear Right // Smart Repair Small	N
12	Bumper Front // Smart Repair Large	Y
133	Bumper Rear // Painting	Y
271	Bumper Front / Trim Left / Replace	Y
535	Trunk Compartment / Window Shelf / Replace	N

Damage Pictures





Trunk Compartment / Window Shelf / Replace-missing



Bumper Front // Smart Repair Large-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Rear // Painting-scratch



Wing Rear Right / Trim / Replace-scratch



Door Rear Right // Smart Repair Small-scratch