



SKODA OCTAVIA COMBI: GQ-532-EJ

Vinnumber:	TMBJG8NX0PY144440	Versionname:	SKODA OCTAVIA COMBI 2.0 TDI 116 BVM6 Business VP [5P] bvm 6-116CH-6cv (break)
First Registrationdate:	12/07/2023	Fiscalpower:	
Expertise Mileage:	123513	Power Kw:	85
Bodytype:	Break	Body colour:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Interior colour:	Dark Grey
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Type of climate control	Autom climate control		

Tyres

	205/60/16/96 V			
Summer tyres:	Fr.L.	Firestone: 25%	Fr.R.	Firestone: 40%
	Re.L.	Firestone: 25%	Re.R.	Firestone: 20%
Tyre profile depth FL				6.7
Tyre profile depth FR				5.6
Tyre profile depth RL				6.4
Tyre profile depth RR				6.9
Tyre size FL				205/60 R 16 96 V
Tyre size FR				205/60 R 16 96 V
Tyre size RL				205/60 R 16 96 V
Tyre size RR				205/60 R 16 96 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				258
Tyre make FR				258
Tyre make RL				258
Tyre make RR				258

Assistance equipment

Spare wheel	Yes	Jack	Yes
Interior, Stain, Cleaning			





Door RL, Dent(s), Repair and paint (complete)



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Polish



Bumper F, Scratch(es), Paint



Bumper moulding FL, Scratch(es), Replace



Bumper R, Scratch(es), Paint



Rear upper boot lining, Scratch(es), Replace



Internal boot lining R, Scratch(es), Acceptable



Internal boot lining L, Scratch(es), Acceptable



Historique Maintenance

Immatriculation: **GQ-532-EJ** Date de 1ère immatriculation: **12/07/2023**

Modèle: **Skoda OCTAVIA COMBI 2.0 TDI 116 BVM6 Business VP [5P] bvm 6-116CH-6cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
24/03/2026	116.388	ESPACE AUTO 31 LABEGE	REVISION ET CLIM
	0		PLAQUETTES AR RPLT
	0		DISQUES PLAQUETTES AV RPLT
	0		BALAI ESSUIE GLACE AR
	0		LIQUIDE DE FREIN
18/09/2025	92.588	AUTO REAL 31	CEINTURE DE SECURITE RPLT
	0		DIAG
24/06/2025	85.713	AUTO REAL 31	REVISION ET CLIM ET AIR ET CARBURANT
	0		BALAIS ESSUIE GLACE AV
	0		ADBLUE
31/10/2024	59.219	AUTO REAL 31	BALAI ESSUIE GLACE AR
	0		REVISION ET CLIM
21/02/2024	28.594	ESPACE RC AUTOMOBILES	REVISION
	0		BALAIS ESSUIE GLACE AV