



DS 7 CROSSBACK: GD-091-MX

Vinnumber:	VR1JCYHZUMY003594	Versionname:	DS DS 7 CROSSBACK BlueHdi 130 Automatique BUSINESS VP [5P] bva 8-130CH-7cv (SUV)
First Registrationdate:	13/12/2021	Fiscalpower:	
Expertise Mileage:	115564	Power Kw:	96
Bodytype:	SUV	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Seats electric F L	
GPS big screen color		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Headlights Xenon/LED/Laser	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	Lining Other
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	225/55/18/102 V			
Summer tyres:	Fr.L.	Michelin: 30%	Fr.R.	Michelin: 35%
	Re.L.	Michelin: 25%	Re.R.	Michelin: 25%
Tyre profile depth FL				6.1
Tyre profile depth FR				5.9
Tyre profile depth RL				6.5
Tyre profile depth RR				6.7
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Roof liner, Stain, Cleaning



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door RL, Scratch(es), Acceptable



Bonnet, Scratch(es), Paint



Bumper moulding FL, Scratch(es), Replace



Door FR, Scratch(es), Paint



Door FR, Scratch(es), Paint





Wing trim RR, Scratch(es), Replace



Wing RR, Scratch(es), Paint



Bumper R, Scratch(es), Paint



Bumper R, Deformed / Strained, Repair and paint (complete)



Historique Maintenance

Immatriculation: **GD-091-MX** Date de 1ère immatriculation: **13/12/2021**

Modèle: **DS 7 CROSSBACK BlueHdi 130 Automatique BUSINESS VP [5P] bva 8-130CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
19/05/2025	90.000	BERREZAI S A S	REVISION ET CLIM ET AIR ET CARBURANT
	0		DIVERS CLIM
	0		LIQUIDE DE FREIN
21/05/2024	59.985	BERREZAI S A S	REVISION
	0		FILTRE CLIM RPLT
18/10/2023	51.284	BERREZAI S A S	REVISION
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		REVISION
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN
	0		FILTRE A AIR RPLT
01/12/2022	26.158	BERREZAI S A S	REVISION
	0		BALAIS ESSUIE GLACE AV