



PEUGEOT 308 3

VIN	VR3F3DGX6RY596336
Première immatriculation	23/08/2024

DÉTAILS DE L'INSPECTION

Date de l'inspection	27/11/2025 10:46:49	Adresse d'inspection
----------------------	---------------------	----------------------

INFORMATIONS SUR LE VÉHICULE

VIN	VR3F3DGX6RY596336	Transmission	Avant
Type de carrosserie	Berline	Nbre sièges	5
Nbre portes	5	Nombre appuis-têtes	5
Première immatriculation	23/08/2024	Couleur intérieur	Noir
Type de carburant	Hybride rechargeable	Couleur carrosserie	Blanc
Marque	PEUGEOT	Catégorie	Vehicule particulier
Modèle	308 3	Couleur tableau de bord	Noir
Boîte de vitesses	Automatique		

DOCUMENTS ET CLÉS

Carnet d'entretien	Oui	Manuel d'utilisation	Oui
Nbre clés total	2	Certificat immatriculation (original)	Original
Nbre clés télécommandes	2	Certificat immatriculation (original)	Oui

OPTIONS

Nature de peinture	Metallisé
--------------------	-----------

DAMAGES

Interior



1 | Seat cover FL

Damage type	Stain
Repair mode	Cleaning



2 | Seat cover R

Damage type	Stain
Repair mode	Cleaning



9 | Compressor

Damage type	Missing
Repair mode	Repair/replace (lump sum)



10 | Tyre repair kit

Damage type	Missing
Repair mode	Repair/replace (lump sum)



11 | Boot carpet

Damage type	Stain
Repair mode	Cleaning

Exterior



3 | Alloy rim FL bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



4 | Alloy rim RL bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)




5 | Alloy rim FR bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



6 | Bumper F

Damage type	Scratch(es)
Repair mode	Paint



7 | Bumper moulding F

Damage type	Scratch(es)
Repair mode	Paint



8 | Door FR

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



12 | Bodywork

Damage type	Not original part
Repair mode	Sticker removal small

Commercial photos

