



BMW X1:			
Vinnumber:	WBA71AC0505P83250	Versionname:	sDrive18dA (100 kW)
First Registrationdate:	10/12/2019	Fiscalpower:	
Expertise Mileage:	175010	Power Kw:	100
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2605
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options			
Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/55/17/97 W				
Summer tyres:	Fr.L.	Firestone: 4 mm	Fr.R.	Firestone: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/55 R 17 97 W
Tyre size FR				225/55 R 17 97 W
Tyre size RL				225/55 R 17 97 W
Tyre size RR				225/55 R 17 97 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				258
Tyre make FR				258
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0	
Number of charging cables (rapid charge)	0	
Total cost ex VAT		0,00
Bonnet, Stone chip(s), Acceptable		0,00



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Boot cover, Missing, Acceptable	0,00
---------------------------------	------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Wing RR, Dent(s), Acceptable	0,00
------------------------------	------

