

Vehicle details					
VIN	YSMVSFFR8 SL315112	Registration date	09/12/2025	Exterior Color	
Brand	Polestar	Licence Plate	N/A	Odometer	29 766 km
Model	POLESTAR 2 LRDM Perf. Plus (FF / 350 kW (476 PS))	Condition of the car	Mit Schaden		
Pre-damage		Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details
































Removable element	Technical Document
Spare wheel kit	User manual
Toolkit	Warranty booklet
Triangle	Log books
Rear parcel shelf	First aid kit
Floor mat BR	Inspektion
Floor mat BL	Ladekabel Starkstrom-Steckdose
Floor mat FR	
Floor mat FL	

Tyres




Exterior

1		Part	Alloy wheel 20"	Repair Time	0.40	Part Cost	-
		Position	Front left	Repair Cost	36.00€	Net Cost	216.00€
		Damages	Scratched	Paint Time	1.60		
		Comments	-	Paint cost	180.00€		
				Flat Rate	-		
2		Part	Door	Repair Time	1.10	Part Cost	-
		Position	Front left	Repair Cost	99.00€	Net Cost	267.75€
		Damages	Scratched	Paint Time	1.50		
		Comments	-	Paint cost	168.75€		
				Flat Rate	-		
3		Part	Door badge	Repair Time	0.20	Part Cost	4.57€
		Position	Front left	Repair Cost	18.00€	Net Cost	22.57€
		Damages	Replace	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	-		
4		Part	Tailgate / Boot door	Repair Time	0.60	Part Cost	-
		Position	-	Repair Cost	54.00€	Net Cost	54.00€
		Damages	Dented - Smart repair	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	54.00€		
5		Part	Door	Repair Time	0.60	Part Cost	-
		Position	Front right	Repair Cost	54.00€	Net Cost	54.00€
		Damages	Dented - Smart repair	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	54.00€		

Others

6		Part	Paint preparation	Repair Time	-	Part Cost	-
		Position	-	Repair Cost	-	Net Cost	168.75€
		Damages	Paintworks	Paint Time	1.50		
		Comments	-	Paint cost	168.75€		
				Flat Rate	-		

Estimated repair cost

Total 783.07€